

STC Listing

Supplemental Type Certificates hold by the SA Group



The Scandinavian Avionics Group

Headquarter Billund Airport Tel.: +45 79 50 80 00
Stratusvej 9 Fax: +45 79 50 80 99
DK-7190 Billund Email: sa@scanav.com
Denmark Web: www.scanav.com

The SA STC Listing

In this document you can find all Supplemental Type Certificates and minor changes that The SA Group currently holds.

If a specific STC does not appear on the list please do not hesitate to contact us as we will be happy to assist you with any requirements you might have via our Part-21 Design approval.



	PT:	Owner:
01-2000 17.02.2000 JETSTREAM3102	PT: 	Allied Signal MK VI GPWS installation. Validation of FAA STC SA00010SE with minor changes. Owner: 99999 Scandinavian Avionics A/S
02-2001 04.01.2001 501	PT: 	Installation of 2 Garmin GNS-430 COM/NAV/GPS. GPS approved for B-RNAV operation. Owner: 99999 Scandinavian Avionics A/S
03-2001 04.01.2001 501	PT: 	Installation of 2 Allied Signal KT70 Mode-S Transponder Owner: 99999 Scandinavian Avionics A/S
04-2001 05.01.2001 421B	PT: 	Installation of Garmin GS-430 COM/NAV/GPS. GPS approved for B-RNAV operation. Owner: 99999 Scandinavian Avionics A/S
09-2002 12.04.2002 551	PT:OY-PDN 551-0412 OY-PDN	Installation of a top mounted transponder (XPDR) antenna with cable through forward bulk head. Owner: 99999 Scandinavian Avionics A/S
1/91 30.01.1991 550	PT: 	Installation of Bendix King KNS-660 Owner: 99999 Scandinavian Avionics A/S
1/93 12.02.1993 F27100 F27MK200	PT: 	Installation of ICARUS 6200 Altitude Alert System Owner: 99999 Scandinavian Avionics A/S
10-2003 08.04.2003 SA227-AC SA227-AT SA227-BC SA227-DC SA227-ST SA227-TT	PT: 	Installation of Fairchild F800 Flight Data Recorder. Owner: 99999 Scandinavian Avionics A/S
10/91 25.06.1999	PT: 	Installation of Fairchild Cockpit Voice Recorder 93A100 and Digital Flight Data Recorder 17M700-274 Owner: 99999 Scandinavian Avionics A/S



10/91 25.06.1999	PT:	Installation of Fairchild Cockpit Voice Recorder 93A100 and Digital Flight Data Recorder 17M700-274 Owner: 99999 Scandinavian Avionics A/S
1900		
10/98 17.04.1998	PT:	Modification of Bendix/King KLN 90B for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
501		
11/89 (Rev. 1) 04.10.1994	PT:	STC issued for type B300 Installation of CVR Fairchild Model 93A-100 and FDR Sundstrand Model FA 542 Owner: 99999 Scandinavian Avionics A/S
300 B300		
12-2002 12.04.2002	PT:	Installation of BF Goodrich Skywatch system Owner: 99999 Scandinavian Avionics A/S
551		
12/93 20.08.1993	PT:	Installation of Honeywell P701 Weather Radar and Data Nav III Owner: 99999 Scandinavian Avionics A/S
AS365N2		
13-2001	PT:	Installation of Thrane & Thrane SATCOM Aero M system Owner: 99999 Scandinavian Avionics A/S
13-2001R1 25.04.2001	PT:OY-LJG 083	Installation of Thrane & Thrane SATCOM Aero M system Owner: 99999 Scandinavian Avionics A/S
LEARJET45	OY-LJG	
13/93 20.08.1993	PT:	Installation of RACAL Ltd. R-NAV 2 FMS Owner: 99999 Scandinavian Avionics A/S
AS365N2		
13/94 24.06.1994	PT:	Installation of GPS Antenne Global p/n 121-016759-01 Owner: 99999 Scandinavian Avionics A/S
650		
14/93 20.08.1993	PT:	Installation of RACAL Ltd. Automatic Voice Advisory Device (AVAD) type V 694/6/1. Owner: 99999 Scandinavian Avionics A/S
AS365N2		
14/95 29.05.1995	PT:OY-CCJ 468	Installation of GPS antenna Owner: 99999 Scandinavian Avionics A/S
LEARJET35		



14/98 30.04.1998	PT:	Installation of 1 ea Universal UNS-1D Flight Management System (FMS) with Collins DME42 for B-RNAV navigation Owner: 99999 Scandinavian Avionics A/S
551		
15/95 (Rev.1) 17.11.1995	PT:	Installation of GPS-antenna Owner: 99999 Scandinavian Avionics A/S
SA226-AT SA226-T(B) SA226-TC SA227-AC SA227-BC SA227-DC SA227-TT SA227-AT SA227		
16-2003 27.09.2003	PT:OY-CTC 101	Installation of Honeywell KLN-900 GPS system. Owner: 99999 Scandinavian Avionics A/S
DHC7 DASH 7 DHC7-102 DHC7-103	OY-CBT OY-CBU OY-GRF OY-GRD OY-CTC OY-GRE	
17-2003 27.09.2003	PT:OY-CTC 101	Replacement of Radar Indicator with Honeywell MFRD. Owner: 99999 Scandinavian Avionics A/S
DHC7 DHC7-102 DHC7-103 DASH 7	OY-CBT OY-CBU OY-GRF OY-GRD OY-CTC OY-GRE	
17/1998 05.05.1998	PT:	Installation of Universal Avionics System Corporation Dual UNS-1D Flight Management System (FMS) for B-RNAV navigation. Owner: 99999 Scandinavian Avionics A/S
FALCON20-D		
17/98 05.05.1998	PT:	Installation of Universal Avionics System Corporation Dual UNS-1D Flight Management System (FMS) for B-RNAV navigation. Owner: 99999 Scandinavian Avionics A/S
FALCON20-F5 FALCON20-D FALCON20-E5		
18-2001 05.10.2001	PT:OY-LJF 173	Installation of Thrane & Thrane SATCOM TT-3000M Aero-M system. Owner: 99999 Scandinavian Avionics A/S



18-2001 05.10.2001	PT: OY-LJF 173	Installation of Thrane & Thrane SATCOM TT-3000M Aero-M system. Owner: 99999 Scandinavian Avionics A/S
Learjet60		
19-2003 25.09.2003	PT:	Installation of 1 each Digital Flight Recorder (DFDR) Fairchild F-1000 system Owner: 99999 Scandinavian Avionics A/S
707-328 707-366 707-300 707-320C 707-366C		
19/92 02.08.1994	PT:	STC issued for type B300 Installation of cockpit voice recorder and flight data recorder Owner: 99999 Scandinavian Avionics A/S
300 350 B300		
19/93 26.05.1994	PT:	Installation of GPS Antenna Owner: 99999 Scandinavian Avionics A/S
65 90 99 100 58P 300 1900 F90 2000 400A A60 B60 200		
20-2000 16.03.2006	PT:	Owner: 99999 Scandinavian Avionics A/S
20-2000R1 08.01.2001	PT: OY-PHN 209	Installation of Universal UNS-K Flight Management System (FMS) with GPS. Approval to carry out B-RNAV operations and GPS "Non-precision Approches" (GPS overlay - and stand-alone procedures). Owner: 99999 Scandinavian Avionics A/S
FALCON10	OY-PHN	
20-98 23.07.1998	PT:	Installation of Allied Signal (Bendix King) KLN 90B GPS for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
500		



20-99 16.03.2006	PT:	Installation of Garmin GPS 155XL and GPS antenna for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
20-99R1 . . .	PT:	Installation of Garmin GPS 155XL and GPS antenna for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
20-99R2 03.11.2000 421 421A 421B 421C	PT:	Installation of Garmin GPS 155XL and GPS antenna for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
2004-8907 17.08.2004 200	PT: SE-LKY BB1221 SE-LTL SE-LKY	Prototp: SE-LKY Installation of Garmin GNS 430 with Avidyne display Owner: 99999 Scandinavian Avionics A/S
2005-2213 07.03.2005 AS365 AS365N1 AS365N2 AS365N	PT: OY-HLL 6420 OY-HRH TF-HDU	Installation of ARTEX C406-2AF ELT Owner: 63605 Scandinavian Avionics
2014341-EO-01 02.12.2008 400A	PT: OY-JJO 267 OY-JJO	Minor change to LBA STC TA0796 for new location of FDR and Electical alt and airspeed Owner: 63605 Scandinavian Avionics
2014661-EO 21.07.2008 AS332L1 AS332L2	PT: LN-OHE 2474 LN-OHE	NUP 2 transponder installation Owner: 63605 Scandinavian Avionics
2014750-EO-02 20.11.2004 S76A	PT: SE-JUC 760219 SE-JUC	Minor NVG provision Owner:
2015055 MCH 06.09.2006 650	PT: OY-NLA 650-0070 OY-NLA	Minor change to EASA.A.S.01191 moving the TCAS and Transponders to the LH nose compartment Owner: 63605 Scandinavian Avionics
2015555-EO-03 26.06.2005 S61	PT: OY-HAF 61267 OY-HAF	VDL Mode 4. AFM EASA.R.A.01047 Owner: 63605 Scandinavian Avionics



2015555-EO-03 26.06.2005 S61N	PT: OY-HAF 61267 OY-HAG	VDL Mode 4. AFM EASA.R.A.01047 Owner: 63605 Scandinavian Avionics
2017016-EO-02 02.12.2008 400A	PT: OY-JJO RK267 OY-JJO	Minor change to EASA STC EASA.A.S.00239R1 for new annunciator swiching Owner: 63605 Scandinavian Avionics
2017860-EO-02 24.07.2008 AS365N AS365N1 AS365N2 AS365N3	PT: LN-OCO 6420 LN-OCO	Minor change for installation of Honeyell MK III Observer. RFM approved under EASA.R.A.01354 Owner: 63605 Scandinavian Avionics
2017860-EO-07 20.11.2007 SA365N SA365N1 AS365N2 AS365N3	PT: LN-OCO 6420 LN-OCO	Minor change for installation of Heel system. AFM approved under EASA.R.A.01361 Owner: 63605 Scandinavian Avionics
2018778-01 MCH 17.11.2005 550 560ULTRA S550 550	PT: SE-RCI 0678 SE-RCI SE-RGY	Minor change to EASA.A.S.0097 FDR 15 parameter Owner: 63605 Scandinavian Avionics
2018778-EO MCH 5 08.07.2008 550 S550 550BRAVO 560 560ULTRA	PT: VP-CSN 560-0401 VP-CSN	Minor change 5 to EASA.A.S.0097R1 Owner: 63605 Scandinavian Avionics
2018778-EO-01 10.08.2007 550 S550	PT: VP-CJR 550-0354 VP-CJR	Minor change to EASA.A.S.0097R1 add of electrical interface for altitude and airspeed. And add of mechanical installation bihind baggage compartment Owner: 63605 Scandinavian Avionics
2019630-EO-02 10.09.2008 LEARJET55A LEARJET55C	PT: OE-GCF 55C136 OE-GCF	Minor change for EASA.A.S.1029 for new location in cabin and 15 parameters. Owner: 63605 Scandinavian Avionics



2019630-EO-02 10.09.2008	PT:OE-GCF 55C136	Minor change for EASA.A.S.1029 for new location in cabin and 15 parameters. Owner: 63605 Scandinavian Avionics
LEARJET55B		
2019630-EO-03 10.09.2008	PT:OE-GCF 55C136	Minor change to EASA.A.S.01032 for adding different Radar addapter (WXA-1000) Owner: 63605 Scandinavian Avionics
LEARJET55A LEARJET55C LEARJET55B		
2019974-EO-04 18.03.2005	PT:D-IDBW 0044	SATCOM antenna Owner: 63605 Scandinavian Avionics
525 D-IDBW		
2019974-EO-06 18.03.2005	PT:D-IDBW 0044	Installation of Kanad ELT 406. 525A added with minor change AFM approved on EASA.A.A.01598 Owner: 63605 Scandinavian Avionics
525 525A D-IDBW G-EDCL		
2019992-EO-01 03.08.2007	PT:SE-DLZ 500-0411	Minor change to EASA.A.S.0576R2 TCAS installation. Move TCAS and Transponder units to the rear of the aircraft. This option CAN only be used if existing shelf is found installed in the aircraft ref Technical order Owner: 63605 Scandinavian Avionics
500 550 S550		
2020221-EO-02 07.02.2005	PT:EC-IMF 0443	406ELT with out remote switch Owner: 63605 Scandinavian Avionics
550 EC-IMF		
2021128-EO-03 16.07.2007	PT:SX-ECG BB-372	Minor change to EASA.A.S.01093R1 for new antenna location of top transponder antenna Owner: 63605 Scandinavian Avionics
200 200C B200 B200C SX-ECG		
2022014-EO MCH 11.03.2008	PT:YU-BZZ 550-0924	Minor change 3 to EASA.A.S.01189R1 (ELT 406 Kannad) introducing high speed antenna Owner: 63605 Scandinavian Avionics
500 550 550BRAVO S550 560 560ULTRA		



2023423-EO-01

24.04.2008

PT: SE-KOL

FA-189

Minor change for EASA.A.S.01216 TCAS STC for having transponders mounted in the nose by adding EASA.A.S.01093R1

Owner: 63605 Scandinavian Avionics

B300
300LW

2023647-EO-01

12.01.2006

PT: SX-HIN

5406

ELT Kannad 406

Owner: 63605 Scandinavian Avionics

AS350B SX-HIN
AS350B1 SX-HFA
AS350B2 SX-HFB
AS350B3 HB-ZKX
AS350BA
AS355F1
AS355F2
AS355N
AS350B4
AS350BB
EC130B4
AS355E
AS355F

2023647-EO-01 MCH

24.07.2009

PT: HB-ZKX

2301

MCH 1 to Kannad ELT installation.

Owner: 63605 Scandinavian Avionics

AS350BA
AS350B
AS350B1
AS350B2
AS350B3
AS350B4
AS350BB
AS350D
EC130B4
AS355E
AS355F
AS355F1
AS355F2
AS355N
AS355NP

2024345-EO-01

19.12.2004

PT:

GPS antenna and provision of wiring
Minor GPS antenna provision

Owner:

ATP OY-SVU
OY-SVT
OY-SVI

2025716-EO-02

06.07.2005

PT: VP-CMP

257214

ELT 406. AFM EASA.A.A.01034

Owner: 63605 Scandinavian Avionics

HS125-700 VP-CMP
HS125-700A OY-MFL
HS125-700B
HS125-800



2025716-EO-02	PT: VP-CMP	ELT 406. AFM EASA.A.A.01034
06.07.2005	257214	Owner: 63605 Scandinavian Avionics
HS125-800A		
HS125-800B		
2025739-EO-01	PT: OY-ASY	ELT Kannad 406
13.01.2006	110-308/19	Owner: 63605 Scandinavian Avionics
EMB110P1	OY-ASY	
EMB110P2	OY-BHT	
2025849-EO-01	PT: LN-AEY	Installation of 1 GTX-330 Mode-S transponder. AFM is approved under EASA.A.A.01226
10.10.2006	31-457	Owner: 63605 Scandinavian Avionics
PA31	LN-AEY	
PA31-325		
PA31-350		
2026288-EO-01	PT: SE-KXM	Minor change to EASA.A.S.01271 for only one transponder mounted in centre pedestal.
18.01.2008	BB-459	Owner: 63605 Scandinavian Avionics
200	SE-KXM	
200C		
B200		
B200C		
300		
300LW		
B300		
B300C		
2026288-EO-03	PT: I-PIAH	ELT 406
23.05.2005	BB777	Owner: 63605 Scandinavian Avionics
200	I-PIAH	
B200	TF-FMS	
200C	F-GICA	
B200C	ln-tw1	
300	SE-KXM	
B300	OH-BSA	
300LW	OH-BSB	
	LN-SUZ	
	LN-NOA	
2026473-EO-01	PT: OY-PBI	ELT 406 AFM EASA.A.A.01025
19.09.2005	871936	Owner: 63605 Scandinavian Avionics
L410 UVP-E20	OY-PBI	
	OY-PBH	
2026480-EO-01	PT: OY-PBW	Installation of Kannad 406 ELT AFM approval is EASA.A.A.01230
31.05.2006	SH3760	Owner: 63605 Scandinavian Avionics
SD3-60	OY-MUG	
SD3-30	OY-PBW	
SD3-60SHERPA	OY-PBV	
SD3-SHERPA	G-BPFN	



2026780-EO-01	PT: SX-HCK	ELT Kannad 406
12.01.2006	593	Owner: 63605 Scandinavian Avionics
BO105A	SX-HET	
BO105C	SX-HAY	
BO105 LS A-1	SX-HMK	
BO105D	SX-HCK	
BO105S		
BO105 CBS-4		
BO105		

2026780-EO-01 MCH	PT: SX-HPB	Minor change for ELT installation. Minor change to 2026780-EO-01 for a new location of unit and antenna.
20.11.2008	S-899	Owner: 63605 Scandinavian Avionics
BO105A	SX-HPB	
BO105C		
BO105D		
BO105S		
BO105 LS A-1		
BO105 CBS-5		
BO105 CBS-4		

2026957-EO-01	PT: OO-SKV	GPS 400 Stand alone
06.06.2005	0153	Owner: 63605 Scandinavian Avionics
500	OY-VIS	
550	OO-SKP	
560	OO-SKV	
S550		

2027045-EO-01	PT: OY-BJP	Minor change ELT installation. AFM approved under EASA.A.A.01070
22.06.2005	AC-499	Owner: 63605 Scandinavian Avionics
SA226-AT	oy-bjp	
SA226-T(B)		
SA226-TC		
SA227-AC		
SA227-AT		
SA227-BC		
SA227-DC		
SA26-AT		

2027113-01 MCH	PT: HA-YFE	Minor Change to STC 1537 for moving antenna installations
28.06.2006	A046SA	Owner: 63605 Scandinavian Avionics
MU300	HA-YFE	
MU300-10	OH-KNE	

2027438-EO-03	PT: OY-BSO	Audio Panel GMA 340. AFM EASA.A.A.01032
18.08.2005	340A-0666	Owner: 63605 Scandinavian Avionics
320	OY-BSO	
340		
340A		
340B		
310		



2027438-EO-03

PT: OY-BSO

Audio Panel GMA 340. AFM EASA.A.A.01032

18.08.2005

340A-0666

Owner: 63605 Scandinavian Avionics

- 310K
- 310P
- 310Q
- 310R
- T310P
- T310Q
- T310R
- 335
- 401
- 401A
- 401B
- 402
- 402A
- 402B
- 402C
- 404
- F406
- 411
- 411A
- 414
- 414A
- 421
- 421A
- 421B
- 421C
- 425
- 441

2027438-EO-05

PT: OY-BSO

Stormscope WX-500. AFM EASA.A.A.01032

15.08.2005

340A-0666

Owner: 63605 Scandinavian Avionics

- 320
- 340
- 340A
- 340B
- 310
- 310K
- 310P
- 310Q
- 310R
- 335
- T310P
- T310Q
- T310R
- 411
- 401
- 401A
- 401B
- 402
- 402A
- 402B
- 402C
- 404

OY-BSO



2027438-EO-05	PT: OY-BSO	Stormscope WX-500. AFM EASA.A.A.01032
15.08.2005	340A-0666	Owner: 63605 Scandinavian Avionics
F406		
411A		
414		
414A		
421		
421A		
421B		
421C		
425		
441		
2027746-EO-02	PT: SE-RBK	Minor change for EASA STC EASA.A.S.01451. New AFM approved under EASA.A.A.01438
10.03.2007	550-0315	Owner: 63605 Scandinavian Avionics
500	SE-RBK	
550		
S550		
550BRAVO		
2027785-EO-01	PT: LH-PBF	ELT 406. AFM EASA.A.A.01036
27.06.2005		Owner: 63605 Scandinavian Avionics
208	LN-PBF	
208A		
208B		
2027788-EO-01	PT: G-DUOE	SELCAL installation
20.09.2005	10052	Owner: 63605 Scandinavian Avionics
CL600-2C10	G-DUOE	
CRJ700		
2027788-EO-02	PT: G-DUOD	HF installation
16.11.2005	10048	Owner: 63605 Scandinavian Avionics
CL600-2C10	G-DUOD	
CRJ700		
2028154-EO-01	PT: OY-PBG	ELT 406. AFM EASA.A.A.01037
21.09.2005	0015	Owner: 63605 Scandinavian Avionics
404	OY-PBG	
406		
F406		
2028478-EO MCH 1	PT: LN-OGL	Minor change for new location of VHF antenna and radio
18.11.2008	3792	Owner: 63605 Scandinavian Avionics
AS350B	LN-OGL	
AS350B1	LN-OMV	
AS350B2	LN-OFB	
AS350B3	LN-OTR	
AS350B4	LN-OFB	
AS350BA	LN-OWC	
AS350BB		
AS350D		



2028478-EO MCH 1	PT:LN-OGL	Minor change for new location of VHF antenna and radio
18.11.2008	3792	
		Owner: 63605 Scandinavian Avionics
AS355E		
AS355F		
AS355F1		
AS355F2		
AS355N		
2028478-EO-01	PT:OY-HIZ	Installation of TFM-138B VHF FM Transceiver.
23.02.2006	3727	
		AFM approved under EASA.A.A.01048
		Owner: 63605 Scandinavian Avionics
AS350B	OY-HIZ	
AS350B1	OY-HGN	
AS350B2	OY-HGO	
AS350B3	OY-HGP	
AS350BA	OY-HGS	
AS350BB	OY-HGR	
EC130B4	OY-HGT	
AS350D	LN-OMD	
AS355E	LN-OPA	
AS355F	LN-OAK	
AS355F1		
AS355F2		
AS355N		
2028531-EO-02	PT:OY-JPJ	SATCOM Provision
26.08.2005	650-0060	
		Owner: 63605 Scandinavian Avionics
650	OY-JPJ	
2028531-EO-01	PT:OY-JPJ	SATCOM, IRIDIUM
27.09.2005	650-0060	
		Owner: 63605 Scandinavian Avionics
650	OY-JPJ	
	OY-NLA	
	OY-EDP	
2029510-EO-01	PT:SE-JOZ	COMM, XPDR, ICS, DG, Horizon
07.10.2005		
		Owner: 63605 Scandinavian Avionics
EC120B		
2029534-EO-02	PT:OE-GTM	FDR and FDAU provision
05.10.2005	RK343	
		Owner: 63605 Scandinavian Avionics
400A	OE-GTM	
2029789-EO-03	PT:SE-IUC	ELT 406 minor change. AFM EASA.A.A.01108
23.12.2005	3447013	
		Owner: 63605 Scandinavian Avionics
PA34-200	SE-IUC	
PA34-200T		
PA34-220T		
2029789-EO-02	PT:SE-IUC	KT 73 Mode-S transponder Minor change. AFM EASA.A.A.01110
23.12.2006	3447013	
		Owner: 63605 Scandinavian Avionics



2029789-EO-02	PT: SE-IUC	KT 73 Mode-S transponder Minor change. AFM
23.12.2006	3447013	EASA.A.A.01110
		Owner: 63605 Scandinavian Avionics
PA34-200	SE-IUC	
PA34-200T		
PA34-220T		
2030000-EO-01	PT: YU-BSM	In-Flight Entertainment system installation
08.12.2005	550-0808	Owner: 63605 Scandinavian Avionics
550	YU-BSM	
S550	YU-BSG	
550BRAVO		
560		
560ULTRA		
2030084-EO-01	PT: LN-AWA	ELT 406 minor change. AFM EASA.A.A.01118
10.01.2006	B-213	Owner: 63605 Scandinavian Avionics
100	LN-AWA	
99		
A100		
B100		
2030182-EO-01	PT: OY-HJP	Moving of Misc. Control panl and C/B panel
18.10.2005	6655	Owner: 63605 Scandinavian Avionics
206L	OY-HJP	
206L3	OY-HPJ	
206L1		
2030241-EO-01	PT: YU-BTT	ELT Kannad 406 installation. AFM
21.02.2006	551-0038	EASA.A.A.01159
		Owner: 63605 Scandinavian Avionics
501	OY-PDN	
551	PH-DEZ	
	YU-BTT	
2030827-EO-01	PT: YU-BSM	SATCOM installation
08.12.2005	550-0808	Owner: 63605 Scandinavian Avionics
550	YU-BSM	
S550	OY-VIS	
560	OY-KLG	
560ULTRA	F-HCRT	
550BRAVO		
2030827-EO-01 MCH 1	PT: VP-CSN	Minor change to 2030827-EO-01 installation of Sky Connect SATCOM
08.07.2008	560-0401	Owner: 63605 Scandinavian Avionics
560	VP-CSN	
560ULTRA	OY-KLG	
2031449-EO	PT: LN-TWL	Minor change for installation of AIM 1100 and PS-835D. AFM approved under EASA.A.A.01335
24.11.2006	BB-1144	Owner: 63605 Scandinavian Avionics
200	ln-twl	
200C	SE-LLU	



2032192-EO	PT: OY-CBT	Upgrade of Com # 1 & 2 for 8.33KHz
13.05.2006	10	Owner: 63605 Scandinavian Avionics
DHC7-102	OY-CBT	
DHC7-103	OY-CBU	
	OY-GRF	
	OY-GRD	
	OY-CTC	
	OY-GRE	
2032349-EO	PT: OE-GMS	Minor change for EASA.A.S.02251 installation of UNS-1E
23.11.2007	341	Owner: 63605 Scandinavian Avionics
Learjet35	OE-GMS	
Learjet35A		
2032575-EO-01	PT: G-JETO	Installation of KY 196B for 8.33KHz
13.04.2006	550-0441	Owner: 63605 Scandinavian Avionics
500	G-JETO	
501		
550		
551		
S550		
2032855-EO	PT: SE-DYO	Satcom antenna installation
12.04.2006	S550-0134	Owner: 63605 Scandinavian Avionics
500	SE-RIM	
550	SE-DLZ	
S550		
550BRAVO		
560-V		
560ULTRA		
2033234 MCH	PT: OY-MUG	Minor change to EASA.A.S.02654. new location of units
28.07.2006	SH3716	Owner: 63605 Scandinavian Avionics
SD3-30	OY-MUG	
SD3-60		
SD3-60SHERPA		
SD3-SHERPA		
2033234 MCH-2	PT: D-CRAS	Minor change for EASA.A.S.02654 for new lampformat and move DSU unit to new location. AFM is approved under EASA.A.A.01354
22.06.2007	SH3744	Owner: 63605 Scandinavian Avionics
SD3-30	D-CRAS	
SD3-60	D-CCAS	
SD3-60SHERPA		
SD3-SHERPA		
2033451-EO	PT: LN-BER	Installation of Stand alone GPS 400
01.06.2006	8192	Owner: 63605 Scandinavian Avionics
DO228-100	LN-BER	
DO228-200	LN-AAO	
DO228-101	VT-EUM	



2033451-EO	PT:LN-BER	Installation of Stand allone GPS 400
01.06.2006	8192	Owner: 63605 Scandinavian Avionics
DO228-201		
DO228-202		
DO228-212		
2033991-EO	PT:SE-DYO	Installation of a Honeywell KLN90B System as stand alone with a single remote indicator. GPS intended for VFR use only. AFM approved under EASA.A.A.01235
21.06.2006	0134	Owner: 63605 Scandinavian Avionics
500	SE-DYO	
550		
S550		
560		
2033992-EO	PT:SE-DYO	Installation of a Concorde model RG-380E sealed lead ACID battery in replacement for the existing nickel cadium battery.
12.06.2006	0134	Owner: 63605 Scandinavian Avionics
500	SE-DYO	
550		
S550		
560		
2034126-MCH	PT:SE-LNU	Adding remote GPS sensor.
12.01.2007	949	Owner: 63605 Scandinavian Avionics
Jetstream3100	SE-LNU	
Jetstream3102	SP-KWF	
Jetstream3103		
Jetstream3200		
Jetstream3201		
2034279-EO	PT:OH-BAR	Installation of GMA 340 audio panel. AFM approved under EASA.A.A.01536
05.06.2007	P-477	Owner: 63605 Scandinavian Avionics
60	OH-BAR	
A60		
B60		
2034421-EO	PT:OY-NLA	Installation of ARTEX 406 MHz ELT
06.09.2006	650-0070	Owner: 63605 Scandinavian Avionics
650	OY-NLA	
2034475-EO	PT:OY-NLA	Moving an Avionics box
06.09.2006	650-0070	Owner: 63605 Scandinavian Avionics
650	OY-NLA	
2034576-EO	PT:LN-OBX	Installation og Homer, UHF and audio selector panel
02.10.2006	2001	Owner: 63605 Scandinavian Avionics
AS332C	LN-OBX	
AS332L		
AS332L1		



2034576-EO 02.10.2006	PT:LN-OBX 2001	Installation og Homer, UHF and audio selector panel Owner:63605 Scandinavian Avionics
SA-330F SA-330G SA-330J		
2034623-EO 02.10.2006	PT:LN-OBX 2001	Installation of Observer Mk III Owner:63605 Scandinavian Avionics
AS332C LN-OBX AS332L AS332L1 SA-330F SA-330G SA-330J		
2034791-EO 28.07.2006	PT:OY-MUG SH3716	Provision for TNL-2000 APP+ GPS system Owner:63605 Scandinavian Avionics
SD3-30 OY-MUG SD3-60 SD3-60SHERPA SD3-SHERPA		
2035111-EO MCH 03.07.2007	PT: SX-DCI 0366	Minor change 1 for EASA.A.S.02791 for new wiring and new AFM. AFM approved under EASA.A.A.01549 Owner:63605 Scandinavian Avionics
550BRAVO SX-DCI 560		
2035168 MCH 14.05.2007	PT: SX-BTO 25033	Minor change to EASA.A.S.02852 Adding new -25 amnd -40 to controleres and new wiring Owner:63605 Scandinavian Avionics
737-300 SX-BTO 737-400 OY-JTB 737-500 737-3Y0		
2035168-EO MCH-4 23.05.2008	PT:OY-JTD MSN24678	Minor change 4 for EASA.A.S.02852 ELS/EHS for adding CTA-100A controller Owner:63605 Scandinavian Avionics
737-300 OY-JTD 737-400 OY-JTA 737-500 737-33A		
2035176-EO 02.10.2006	PT:LN-OBX 2001	Installation og KMD 150 gps for VHF use only Owner:63605 Scandinavian Avionics
AS332C LN-OBX AS332L AS332L1 SA-330F SA-330G SA-330J		



2035914 MCH 16.05.2007	PT: OY-CLP 650-7093	Minor change for EASA.A.S.0253 EGPWS unit is relocated to be installed in LH side aft cabin. Owner: 63605 Scandinavian Avionics
650	OY-CLP	
2035998-EO 06.10.2006	PT: LN-OBX 2001	Installation of VHF FM radio Owner: 63605 Scandinavian Avionics
AS332L AS332C AS332L1 SA-330F SA-330G SA-330J	LN-OBX	
2035999-EO 06.10.2006	PT: LN-OBX 2001	Installation of STCOM and Tracker system Owner: 63605 Scandinavian Avionics
SA-330F SA-330G SA-330J AS332C AS332L AS332L1	LN-OBX	
2036080-EO 27.03.2007	PT: D-CRRR	Minor change for different Dabs for EASA.A.S.02948 Owner: 63605 Scandinavian Avionics
650	D-CRRR	
2036829-EO 10.02.2009	PT: SE-HOJ 760605	Observer MK III RFM approved EASA.R.A.01590 Owner: 63605 Scandinavian Avionics
S76A S76B S76C	SE-HOJ SE-JOB SE-JOJ	
2037403-EO 18.12.2006	PT: OY-RAA 258235	Software upgrade of Universal UNS-1B/B+ for 604.X software. And Universal RTU software upgrade to 2.1 Owner: 63605 Scandinavian Avionics
BAe125-800A BAe125-800B	OY-RAA	
2037470-EO 18.09.2008	PT: SE-ISG 340B-162	Minor change for EASA.A.S.03003 for UNS-1L/K+. AFM approved under EASA.A.A.01942 Owner: 63605 Scandinavian Avionics
SF340A SF340B 340B	SE-ISG XA-TJI	
2037656-EO 07.02.2007	PT: SX-HDA 7422	Minor change for ELT 406 kanard AFM approved under EASA.R.A.01267 Owner: 63605 Scandinavian Avionics
A109 A109A	SX-HDA	

**2037656-EO**

07.02.2007

PT: SX-HDA

7422

Minor change for ELT 406 kanard AFM approved under EASA.R.A.01267

Owner:63605 Scandinavian Avionics

A109All
A109C
A109E
A109K2
A109LUH
A109S
A119

2037657-EO

01.06.2007

PT: SX-HFD

7535

Minor change for installation of Artex 406 ELT

Owner:63605 Scandinavian Avionics

BK117A-1
BK117A-3
BK117A-4
BK117B-1
BK117B-2
BK117C-1
BK117C-2

SX-HFE
SX-HFD

2037689-EO

26.09.2007

PT: 7T-VVI

Minor change to EASA.A.S.03107 for different DAPS. AFM approved under EASA.A.A.01645

Owner:63605 Scandinavian Avionics

650

2037878-EO

22.01.2007

PT: OK-SLS

560-0088

Minor change for installation of temperatur sensor

Owner:63605 Scandinavian Avionics

550
S550
500
560

OK-SLS
I-JESO
SE-DLZ

2038281-EO

10.08.2007

PT: VP-CJR

550-0354

Minor change to installe C/B panel in reight hand instrument panel

Owner:63605 Scandinavian Avionics

550
500
S550

VP-CJR

2038331-EO

07.11.2007

PT: LN-VIP

879

Minor change for 8.33KHz upgrade of Collins VHF-22/CTL-22

Owner:63605 Scandinavian Avionics

Jetstream3102
Jetstream3103
Jetstream3201
Jetstream3100
Jetstream3200

LN-VIP

2038735-EO

12.04.2007

PT: OY-SVM

17274818

Minor Change for Installation of GTX 330 with ELS AFM approved under EASA.A.A.01477

Owner:63605 Scandinavian Avionics

172

OY-SVM



2038735-EO

12.04.2007

PT: OY-SVM

17274818

Minor Change for Installation of GTX 330 with
ELS AFM approved under EASA.A.A.01477

Owner:63605 Scandinavian Avionics

172A
172K
172B
172L
172M
172N
172P
172S
172R
172E
172C
172D
172I
172Q

2039435-EO

10.08.2007

PT: VP-CJR

550-0354

Minor change to move existing PS-835 for the
rear to the avionics compartment in the nose

Owner:63605 Scandinavian Avionics

550

VP-CJR

2039448-EO

08.05.2007

PT: SX-IFA

49809

Minor change for installation of 406 ELT
Kannad. AFM approved under EASA.A.A.01499

Owner:63605 Scandinavian Avionics

717-200
DC9-10
DC9-21
DC9-30
DC9-31
DC9-41
DC9-50
DC9-51
DC9-81
DC9-82
DC9-83
DC9-87
MD-88
MD90-30

SX-IFA

2039628-EO

15.05.2007

PT: D-IIVK

T303-0287

Minor change for GTX-330 transponder with ELS.
AFM approved under EASA.A.A.01510

Owner:63605 Scandinavian Avionics

T303

D-IIVK

2039713-EO

01.05.2007

PT: SE-KDK

BB-909

Minor change for installation of Altitude
encoder no. 2

Owner:63605 Scandinavian Avionics

200
200C
B200
B200C
300



2039713-EO 01.05.2007	PT:SE-KDK BB-909	Minor change for installation of Altitude encoder no. 2 Owner:63605 Scandinavian Avionics
300LW B300 B300C		
2039919-EO 11.05.2007	PT:D-EHVM 236	Minor change for GTX-330 with ELS. AFM Approved under EASA.A.A.01511 Owner:63605 Scandinavian Avionics
35-33 35-B33 35-C33 35-C33A A36 A36TC B36TC E33 F33A F33C J35 N35 P35 V35 V35A V35B 36	D-EHVM	
2040320-EO 31.05.2007	PT:D-EKFC 24-3083	Minor Change for installation of GTX 330 Owner:63605 Scandinavian Avionics
M20 M20A M20B M20C M20D M20E M20F M20G M20J M20K M20L M20M M20R M20S		
2040879-EO 12.09.2007	PT:OY-EDP 650-014	Replacement of existing CVR to CVR-30B. AFM approved under EASA.A.A.01605 Owner:63605 Scandinavian Avionics
650	OY-EDP	
2040892-EO 10.08.2007	PT:LN-FAO 148	Minor change for installation of Kanad 406 ELT. AFM approved under EASA.A.A.01591 Owner:63605 Scandinavian Avionics
ATR42-200	LN-FAO	



2040892-EO 10.08.2007	PT:LN-FAO 148	Minor change for installation of Kanad 406 ELT. AFM approved under EASA.A.A.01591 Owner: 63605 Scandinavian Avionics
ATR42-300 ATR42-320 ATR42-400 ATR42-500		
2041134-EO 04.09.2007	PT:LN-SUN 5517	Minor change for upgrad od Data transfer suystem for Rockwell Collins FMS Owner: 63605 Scandinavian Avionics
CL600-1A11 LN-SUN CL600-2A12 CL600-2B16 CL604 CL601-3A CL601-3R		
2041403-EO-2 20.07.2007	PT:D-GDTD	Minor change for GTX 330 Mode-S transponder AFM approved under EASA.A.A.01578 and EASA.A.A.01668 Owner: 63605 Scandinavian Avionics
2041473-EO 29.08.2007	PT:SE-DRS RK037	Minor change for installation of Kannad 406 ELT Owner: 63605 Scandinavian Avionics
400A SE-DRS 400 SE-RBO		
2041473-EO MCH 18.12.2008	PT:SE-RBO RK303	Minor change for new location of ELT unit on 2047473-EO. Owner: 63605 Scandinavian Avionics
400 SE-RBO 400A		
2042205-EO 17.10.2007	PT:D-ESLO	Minor change for installation of a WX-500. AFM approved under EASA.A.A.01645 Owner: 63605 Scandinavian Avionics
SR20 D-ESLO SR22		
2042581-EO 29.02.2008	PT:F-HALB 1394	Minor change for installation od PMA 7000B audio panel and PXE7300 in-flight entertainment system. AFM approved on EASA.R.A.01460 Owner: 63605 Scandinavian Avionics
EC120B F-HALB		
2042582-EO 22.01.2009	PT:F-HALB 1394	KRA 405B installation for EFIS display Minor Change RFM approved on EASA.R.A.01588 Owner: 63605 Scandinavian Avionics
EC120B F-HALB		



2042583-EO 18.03.2008	PT:F-HALB 1394	Minor change for installation of TAS 600 and Moving terrain. AFM approve on EASA.R.A.01461 Owner: 63605 Scandinavian Avionics
EC120B	F-HALB	
2042607-EO 12.02.2008	PT:SE-RCY 550-0302	Minor change for ELS (only) upgrade of dual MST 67A. AFM approved under EASA.A.A.01756R1 Owner: 63605 Scandinavian Avionics
550	SE-RCY	
2042855-EO-01 14.11.2007	PT:OY-JBJ 258358	Minor Change Provistin of SATCOM reveiver and antenna Owner: 63605 Scandinavian Avionics
Hawker 800XP	OY-JBJ	
2043110-EO 18.03.2008	PT:F-HALB 1394	Minor change for installation of Strobe lights Owner: 63605 Scandinavian Avionics
EC120B	F-HALB	
2043204-EO 19.12.2007	PT:G-BPFN SH-3747	Minor change for installation of dual Mode-S transponders. OBS can only be used where Antenna installation is existing Owner: 63605 Scandinavian Avionics
SD3-60 SD3-60SHERPA SD3-30 SD3-SHERPA	G-BPFN	
2043249-EO 14.11.2007	PT:LN-FAQ 953	Minor change for installation of duall mode-S transponders with ELS. OBS requires Top transponder antenna is installed Owner: 63605 Scandinavian Avionics
Jetstream3102 Jetstream3103 Jetstream3201	LN-FAQ	
2043647-EO 13.11.2007	PT:OY-JBJ 258358	Minor Change to upgrade existing CVR-30B to a CVR-120. AFM approved on EASA.A.A.01665 Owner: 63605 Scandinavian Avionics
Hawker 800XP	OY-JBJ	
2044563-EO 19.03.2008	PT:PH-KMS P21000626	Minor change for installation of TAS 497 displayed on exsisting GNS 430 Owner: 63605 Scandinavian Avionics
p210n P210R	PH-KMS	
2044601-EO 19.02.2008	PT:OH-KOG 642	Minor change for Kanard ELT 406 MHz Owner: 63605 Scandinavian Avionics
DHC6-100 DHC6-200 DHC6-300	OH-KOG SE-GEE	



2044665-EO	PT: OY-JRN	Minor change for GPS antenna installation
11.02.2008	BB-364	Owner: 63605 Scandinavian Avionics
200	OY-JRN	
200C		
B200		
B200C		
2044723-EO	PT: LN-AIR	Minor Change for upgrading for AIRSHOW 4000
25.08.2008	20141	Owner: 63605 Scandinavian Avionics
BD100-1A10	LN-AIR	
2045345-EO	PT: OY-PHN	Minor change to EASA.A.S.01059R1
19.02.2008	209	Owner: 63605 Scandinavian Avionics
Falcon10	OY-PHN	
2045650-EO	PT: I-UJLA	Minor change for Battey replacment. OBS require SB 731
21.04.2008		Owner: 63605 Scandinavian Avionics
Falcon20 GF	I-ULJA	
Falcon20-C		
Falcon20-D		
Falcon20-E		
Falcon20-F		
Falcon20-G		
Falcon20-C5		
Falcon20-D5		
Falcon20-E5		
Falcon20-F5		
Falcon200		
2045668-EO	PT: D-CANC	Minor change for GPS antenna installation
27.02.2008		Owner: 63605 Scandinavian Avionics
SA227-DC	D-CNAC	
2046006-EO	PT: LN-IDA	Minor change for installation of 5 FM VFH antennas for a trackor system and one GPS and one Iridum antenna.
22.04.2008	BL-141	Owner: 63605 Scandinavian Avionics
B200C	LN-IDA	
2046341-EO	PT: SX-IFA	Minor change for ELS upgrade.
28.03.2008	49809	Owner: 63605 Scandinavian Avionics
DC9-10	SX-IFA	
DC9-21		
DC9-31		
DC9-30		
DC9-41		
DC9-50		
DC9-51		
DC9-81		
DC9-82		
DC9-83		
DC9-87		
MD88		



2046341-EO	PT: SX-IFA	Minor change for ELS upgrade.
28.03.2008	49809	Owner: 63605 Scandinavian Avionics
MD90-30		
717-200		
2046476-EO	PT: OY-HPI	Minor change for GNS 430W and GTX 330
15.08.2008	45368	Owner: 63605 Scandinavian Avionics
206	OY-HPI	
206A		
206B		
206L		
206L-1		
206L3		
206L4		
2046477-EO	PT: OY-HPI	Minor change for KR 87 ADF, KN 63 DME and KRA 10A Radio Altimeter
15.08.2008	45368	Owner: 63605 Scandinavian Avionics
206	OY-HPI	
206A		
206B		
206L		
206L-1		
206L3		
206L4		
2046710-EO	PT: OY-FIN	Minor change for GTX 330 Mode-S transponder with ELS.
06.06.2008	359	Owner: 63605 Scandinavian Avionics
112	OY-FIN	
112B		
112A		
112TC		
112TCA		
114		
114A		
114B		
2047346-EO	PT: EI-DXC	Installation of mini QAR installation
26.05.2008	26300	Owner: 63605 Scandinavian Avionics
737-3M8	EI-DXC	
737-36E	EI-DXG	
737-31S	EI-CZG	
737-49R	EI-CXM	
737-48E	EI-DFE	
737-430	EI-DFP	
737-42C	EI-DFD	
737-3Y0	EI-DMR	
737-436	EI-CWX	
737-4S3	EI-CWF	
737-4Q8	EI-CWE	
737-4Y0	D-AGMR	
	EI-COK	
	EI-COJ	



2047346-EO	PT:EI-DXC	Installation of mini QAR installation
26.05.2008	26300	Owner: 63605 Scandinavian Avionics
	EI-COI	
	EI-COH	
	EI-DOV	
	EI-DOS	
	EI-DNX	
	EI-CSU	
	EI-CRZ	
	F-GKTB	
	F-GKTA	
2047353-EO	PT:OY-PEM	Minor change for ELS with GTX 330
18.07.2008	448195020	Owner: 63605 Scandinavian Avionics
PA44-180	OY-PEM	
PA44-180T		
2047615-EO	PT:LN-RUS	Minor change for ELS singel MST 67A and PS 578
04.07.2008		Owner: 63605 Scandinavian Avionics
SF340A	LY-RUS	
340B		
2047748-EO	PT:LN-ACY	Minor change for Replacement of RH altimeter to drum count type
12.12.2008	LW309	Owner: 63605 Scandinavian Avionics
E90	LN-ACY	
B90		
C90		
C90A		
2047800-EO	PT:OY-HPI	Minor change for Kannad 406MHz ELT. RFM approved on EASA.R.A.01536
24.07.2008	45368	Owner: 63605 Scandinavian Avionics
206	OY-HPI	
206A		
206B		
206L-1		
206L3		
206L		
206L4		
2047922-EO	PT:LN-OEI	Kannad 406AF-H ELT installation
19.01.2010	47154	Owner: 63605 Scandinavian Avionics
222	LN-OEI	
222B		
222U		
230		
430		
2047941-EO	PT:SE-LPE	Minor change for KN 62A installation
01.08.2008	17280958	Owner: 63605 Scandinavian Avionics
172R		
172S		
172		



2047941-EO	PT: SE-LPE	Minor change for KN 62A installation
01.08.2008	17280958	Owner: 63605 Scandinavian Avionics
172A		
172B		
172C		
172D		
172E		
172F		
172G		
172I		
172K		
172L		
172M		
172N		
172P		
182S		
182T		
206H		
T206H		
F406		
2048052-EO	PT: SX-BMM	VHF-22A 8.33Khz upgrade.
05.08.2008	BC-774B	Owner: 63605 Scandinavian Avionics
SA-226tc		
SA227-AC		
SA227-BC		
2048549-EO	PT: OY-EEF	Minor change for Installation of SATCOM SB LITE. Only valid for S/N BB-1548. Change is based on Danish ST 3/99.
23.10.2008	BB-1548	Owner: 63605 Scandinavian Avionics
B200	OY-EEF	
2048669-EO	PT: G-ODCM	Minor change for KR 87ADF installation
09.12.2008	525B-0153	Owner: 63605 Scandinavian Avionics
525B	G-ODCM	
2049027-EO	PT: OY-BHU	Minor Change for GPS antenna installation
12.12.2008	7904004	Owner: 63605 Scandinavian Avionics
PA31T1	OY-BHU	
2049080-EO	PT: SX-HPS	Minor change for ARTEX C406-1HM ELT RFM supplement EASA.R.A.01577 Incl MCH 1 2049080-EO-2
19.12.2008	011	Owner: 63605 Scandinavian Avionics
EC135-P1	SX-HPS	
EC135-P2	SX-HPE	
EC135T1	SX-HPD	
EC135T2	LN-OTM	
EC135-P2+		
EC135-T2+		
2049090-EO	PT: D-CGFG	Minor change for FIS-84 installation
05.12.2008	222	Owner: 63605 Scandinavian Avionics



2049090-EO	PT: D-CGFG	Minor change for FIS-84 installation
05.12.2008	222	Owner: 63605 Scandinavian Avionics
Learjet35	D-CGFG	
Learjet35A		
Learjet36		
Learjet36A		
2049173-EO	PT: LN-LMX	Kanad 406MHz ELT Minor Change
16.01.2009	8006	Owner: 63605 Scandinavian Avionics
AP68TP-300	LN-LMX	
2049202-EO	PT: SX-BKU	Minor change for GPS Antenna and Wiring provision.
12.12.2008	25764	Owner: 63605 Scandinavian Avionics
737-300	SX-BKU	
737-400	SX-BMD	
737-500		
737-48E		
2049203-EO	PT: SX-BKU	Minor change for HF installation SAD/SA Greece STC.
09.12.2008	25764	Owner: 63605 Scandinavian Avionics
737-300	SX-BKU	
737-400	SX-BMD	
737-500		
737-48E		
2049259-EO	PT: LN-ORM	Minor change for ELT Kanad 406
20.11.2008	28054	Owner: 63605 Scandinavian Avionics
214B	LN-ORM	
214B-1		
2049299-EO	PT: LN-PBF	Minor change for replacement of LH and RH altimeters to drum counter type. LH with baro pot and encoder
23.09.2008	208B0584	Owner: 63605 Scandinavian Avionics
208	LN-PBO	
208A	LN-PBF	
208B		
2049633-EO	PT: VP-BCL	ARTEX 406 MHz ELT
11.03.2009	10247	Owner: 63605 Scandinavian Avionics
CL600-2B19	VP-BCL	
CL600-2C10		
CL600-2D24		
CL-600-2D15		
2049705-EO	PT: OY-JTA	Minor Change for Mode-S transponder #2 (Honeywell)
05.12.2008	23631	Owner: 63605 Scandinavian Avionics
737-300	OY-JTA	
737-400		
737-500		
737-36Q		



2049705-EO 05.12.2008	PT:OY-JTA 23631	Minor Change for Mode-S transponder #2 (Honeywell) Owner:63605 Scandinavian Avionics
737-33A 737-31S 737-36E 737-36N 737-200		
2049850-EO 28.10.2008	PT:LN-IDA BL-141	RH altimeter replacement for 101735/KA 346 Minor change Owner:63605 Scandinavian Avionics
200 200C B200 B200C 300 300LW B300 B300C 1900C	LN-IDA	
2050244-EO 31.10.2008	PT:OH-BBL E2375	Minor change for 406 Kannad ELT Owner:63605 Scandinavian Avionics
B35 A35 G35 J35 N35 P35 V35A 36 A36 35 S35 VJ35	OH-BBL OH-BBM OH-BBN OH-BBK	
2051078-EO 10.03.2009	PT:SX-RFA 30232/888	AERO M SATCOM Owner:63605 Scandinavian Avionics
757-200 757-300 757-23N 757-208 757-236 757-28A	SX-RFA	
2051086-EO 03.12.2008	PT:OY-JJO RK267	Minor change for Artex ELT. AFM approved under EASA.A.A.02021 Owner:63605 Scandinavian Avionics
400A 400	OY-JJO	



2051645-EO	PT:D-IHBL	GPS and ATC antenna provision
24.04.2009	TT512	Owner: 63605 Scandinavian Avionics
SA226-AT		
SA226-T(B)		
SA26-AT		
SA227-AT		
SA227-TT		
SA26-T		
SA226-T		
2051834-EO	PT:OY-CLP	Minor change for software upgrad of GNS-XL FMS
09.01.2009	650-7093	Owner: 63605 Scandinavian Avionics
650	OY-CLP	
2052325-EO	PT:OY-PCE	ELS with singel existing TDR 94D
06.03.2009	257	Owner: 63605 Scandinavian Avionics
ATR42-200	OY-PCE	
ATR42-300	OY-PCD	
ATR42-320		
ATR42-400		
ATR42-500		
2052327-EO	PT:OY-PCE	KA155 NAV FM filter for KNR634, Honeywell.
13.03.2009	257	Owner: 63605 Scandinavian Avionics
ATR42-200		
ATR42-300		
ATR42-320		
ATR42-400		
ATR42-500		
2052654-EO	PT:OO-LAC	8.33KHz upgrade. Collins VHF-22C and CTL-92C
27.02.2009	BL-16	Owner: 63605 Scandinavian Avionics
200	OO-LAC	
200C		
B200		
B200C		
300		
300LW		
1900C		
2052800-EO	PT:OY-BSO	ELT 406MHz Kannad compact
06.03.2009	340A-0666	Owner: 63605 Scandinavian Avionics
340	OY-BSO	
340A		
2053375-EO	PT:LN-HTD	VHF FM Antenna installation
17.11.2009	T-294	Owner: 63605 Scandinavian Avionics
SA226-AT	LN-HTD	
SA226-T		
SA226-T(B)		
SA226-TC		
2053526-EO	PT:LN-OOH	GPS Data outlet, DME Antenna and DC-DC Converter Installation
12.01.2010	0399	



RFM: STC10028591

Owner: 63605 Scandinavian Avionics

EC135-P1	LN-OOE
EC135-P2	LN-OOH
EC135-P2+	
EC135T1	
EC135T2	
EC135-T2+	

2053673-EO

PT:F-GLPJ

ELT 406 MHZ Kanad AF

21.05.2009

UC-40

Owner: 63605 Scandinavian Avionics

200	F-GLPJ
200C	A6-FCD
B200	A6-FCA
B200C	A6-FCB
300	A6-FCC
300LW	
B300	
B300C	
1900C	

2054075-EO-3

PT:OY-HAG

Blue Sky network Satcom and tracking syst.

20.06.2009

61268

Owner: 63605 Scandinavian Avionics

S61N

2054208-EO

PT:EI-DFP

EFP provision

29.05.2009

A319-112

Owner: 63605 Scandinavian Avionics

A319-112	EI-DFP
A320-212	
A320-214	
A320-231	
A321-211	
A320-231	
A318-111	
A318-112	
A318-121	
A318-122	
A320-111	
A320-211	
A320-216	
A320-232	
A320-233	
A320-233	
A329-215	
A320-215	
A321-111	
A321-112	
A321-131	
A321-212	
A321-213	
A321-231	
A321-232	
A319-111	
A319-113	



2054208-EO	PT: EI-DFP	EFP provision
29.05.2009	A319-112	Owner: 63605 Scandinavian Avionics
A319-114		
A319-131		
A319-132		
A319-133		
2054536-EO	PT: SX-TIC	Cabin seat config. with 456 seats.
04.09.2009	23501	Owner: 63605 Scandinavian Avionics
747-281B1	SX-TID	
2054676-EO	PT: LN-ORM	TFM-138B VHF FM radio with antenna intallation.
23.07.2009	28054	Owner: 63605 Scandinavian Avionics
214B	LN-ORM	
214B-1	LN-OPO	
2054921-EO	PT: SE-LZU	AHAB Hawk Eye II system installation
27.10.2009	11121	Owner: 63605 Scandinavian Avionics
680FL	SE-LZU	
685		
690		
690A		
695		
2055040-EO	PT: SE-RIO	ST3400 TAWS B installation
09.02.2010	0181	Owner: 63605 Scandinavian Avionics
525	SE-RIO	
525A		
2055041-EO	PT: SE-LGX	Replacement of 2 ea 1500VA Static Inverters.
13.04.2010	2036	Owner: 63605 Scandinavian Avionics
ATP		
2057429-EO	PT: SE-LZU	AUX Power outlet and control.
28.10.2009	11121	Owner: 63605 Scandinavian Avionics
690A	SE-LZU	
680FL		
685		
690		
695		
2058057-EO	PT: SX-IFA	IFE upgrade - Only S/N 49809.
12.12.2009	49809	Owner: 63605 Scandinavian Avionics
DC9-83		
2058089-EO-2	PT: SE-RIO	FMS IND. RH HSI and Switch/ann RH side
03.03.2010	0181	Owner: 63605 Scandinavian Avionics
525	SE-RIO	
525A		
2058337-EO	PT: F-HEQA	KHF-950 installation
19.01.2001	525-0024	Owner: 63605 Scandinavian Avionics
525	F-HEQA	



2058337-EO 19.01.2001 525A	PT:F-HEQA 525-0024	KHF-950 installation Owner: 63605 Scandinavian Avionics
2059207-EO 25.03.2010 Falcon2000 FALCON2000EX	PT:OY-CLN 0035 OY-CLN	T&T Satcom upgrade to SB+ Owner: 63605 Scandinavian Avionics
2059305-EO 29.04.2010 DHC6-200 DHC6-300	PT:LN-JMP 0184 LN-JMP	Installation of GTX330, GTX327 and KI204. Owner: 63605 Scandinavian Avionics
2060022-EO 25.03.2010 S76A S76B S76C	PT:SE-JUX 760518 SE-JUX	Alteration to support HEMS operation. Owner: 63605 Scandinavian Avionics
2060597-EO 26.04.2010 AS350B AS350B1 AS350B2 AS350B3 AS350BA AS350BB AS350D	PT:RA-04097	Prima-KV HF installation without antenna. Owner: 63605 Scandinavian Avionics
2060628-EO 25.03.2010 S76A S76B S76C	PT:SE-JUX 760518 SE-JUX	Approval of portable Medical Equipment Owner: 63605 Scandinavian Avionics
21-2000 01.09.2000	PT:OY-PHN 209	Installation of Garmin GNS-530 GPS and COM (VOR/ILS Receiver deactivated). GPS approved for B-RNAV operations. Owner: 99999 Scandinavian Avionics A/S
21/97 (Rev. 2) 23.12.1998 650	PT:	Installation of 1 Universal UNS-1D FMS with Collins DME-42 Owner: 99999 Scandinavian Avionics A/S
23-2000 09.11.2001 Falcon10 Falcon100	PT:OY-PHN 209	Installation of STORMSCOPE WX500 with GNS 530 as Indicator Owner: 99999 Scandinavian Avionics A/S



23-2001 28.09.2001	PT:	Installation of Honeywell EGPWS Mk. VIII system Owner: 63605 Scandinavian Avionics
550 S550		
23-2001R1 19.03.2003	PT:OY-CYV 550-0440	Installation of Honeywell EGPWS Mk. VIII system Owner: 99999 Scandinavian Avionics A/S
550 S550	OY-CYV VP-CJR OY-TMA F-HCRT	
24-2001 13.08.2001	PT:OY-CCJ 468	Installation of Honeywell EGPWS MK VIII Owner: 99999 Scandinavian Avionics A/S
LEARJET35A	OY-CCJ	
24-2002 08.08.2002	PT:	RVSM Non-group Approval per Aerodata Master Document List Falcon 10 RVSM, MDL-A/C-046 Revision 0, dated June 06, 2002. Validation of LBA STC No. TA0608. Owner: 99999 Scandinavian Avionics A/S
FALCON10		
25-2002 11.09.2002	PT:OY-CDN 969	Installation of Garmin GNS-530 and approval for B-RNAV enroute operations. Owner: 99999 Scandinavian Avionics A/S
TB21		
25-99 14.05.1999	PT:OY-SVL	Installation of TNL-2101 Approach Plus GPS for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
501		
26-98 04.06.1998	PT:	Installation of Sundstrand Mark VI Ground Proximity Warning System (GPWS). Owner: 99999 Scandinavian Avionics A/S
FALCON20-E5 FALCON20-F5 FAN JET FALCON FAN JET FALCON FAN JET FALCON		
27-2000 22.09.2000	PT:	Installation of Allied Signal AR-30 Cockpit Voice Recorder system Owner: 99999 Scandinavian Avionics A/S
550	OY-ELY	
28-2000 12.10.2000	PT:OY-ELY 550-0139	Installation of Universal UNS-1K Flight Management System (FMS) with GPS. Approval to carry out B-RNAV operations. Owner: 99999 Scandinavian Avionics A/S
550	OY-ELY	



28-2003	PT: SX-BNN	Installation of Fairchild F-1000 DFDR System.
23.06.2003	BC-771B	Owner: 99999 Scandinavian Avionics A/S
SA227-AC	SX-BNN	
SA227-BC	SX-BMM	
3/90	PT:	Installation of Collins HF-200
04.02.1992		Owner: 99999 Scandinavian Avionics A/S
441		
31-99	PT:	Installation of Ground Proximity Warning System (GPWS) Mark VI. Validation of FAA STC ST87CH with approval of certain derogations from the STC.
16.06.1999		Owner: 99999 Scandinavian Avionics A/S
650		
32-2002	PT: OY-SBT	Installation of Flight Data Recorder Fairchild F-800
24.01.2003	33	Owner: 99999 Scandinavian Avionics A/S
SN 601 CORVETTE	OY-SBT	
33-99	PT:	Installation of Allied Signal (Sundstrand) Ground Proximity Warning System (GPWS) Mark VI. Validation of FAA STC ST157CH with approval of certain degogations frm the STC.
18.06.1999		Owner: 99999 Scandinavian Avionics A/S
560		
34-2003	PT: OY-CTC	Installation of Honeywell EGPWS Mk. VI
27.09.2003	101	Owner: 99999 Scandinavian Avionics A/S
DHC7	OY-CBT	
DASH 7	OY-CBU	
DHC7-102	OY-GRF	
DHC7-103	OY-GRD	
	OY-CTC	
	OY-GRE	
35-2003	PT: OY-SVY	Installation of Trimble TNL-2101 Approach Plus GPS for B-RNAV operation and continued IFR operation
15.12.2003	981	Owner: 99999 Scandinavian Avionics A/S
Jetstream3200	OY-SVR	
Jetstream3201	OY-SVB	
	OY-SVY	
	SX-IDI	
	LN-VIP	
36-2000	PT:	Replacement of the existing glareshield with a new made from fiberglass materiel to accomodate the caution annunciator panel. Validation of FAA "Field Approval" per FAA Form 337 dated June 25, 1993.
11.10.2000		Owner: 99999 Scandinavian Avionics A/S
550	OY-ELY	



36-2001 25.02.2003	PT: OY-ELY 550-0139	Installation of Universal Avionics Terrain Awareness Warning System (TAWS) Owner: 99999 Scandinavian Avionics A/S
550		
37-2000 17.10.2000	PT: OY-ELY 550-0139	Installation of Fairchild F-800 Digital Flight Data Recorder Owner: 99999 Scandinavian Avionics A/S
550	OY-ELY	
38-2003 27.09.2003	PT:	Installation of TAWS Class A, Honeywell E-GPWS Mk. VIII system. Owner: 99999 Scandinavian Avionics A/S
650	OY-NLA	
38-98 29.07.1998	PT:	Installation of Trimble TNL-2000 Approach Plus GPS for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
SA226-AT SA226-T(B) SA227-AT SA227-TT		
38-99 01.11.1999	PT:	Replacement of ADF System for installation of Allied Signal ADF KR87 Owner: 99999 Scandinavian Avionics A/S
B90		
39-2000 07.12.2000	PT: OY-PHN 209	Installation of Alliedsignal GPWS Mk. VI Owner: 99999 Scandinavian Avionics A/S
Falcon10	OY-PHN	
39-2003 27.09.2003	PT: SX-BSR 718	Installation of Honeywell EGPWS Mk. VI, Fairchild F-800 FDR and Artex C406-2 ELT Owner: 99999 Scandinavian Avionics A/S
Jetstream3100	SX-BSR	
39-98 29.07.1998	PT:	Installation of Trimble TNL-2000 Approach Plus GPS for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
SA226-TC SA227-AC SA227-BC		
40-2000 10.11.2000	PT: OY-ELY 550-0139	Installation of Garmin GNS-530 GPS (VOR/ILS Receiver and COM Transiever deactivated). GPS approved for B-RNAV operations. Owner: 99999 Scandinavian Avionics A/S
550	OY-ELY	
40-98 29.07.1998	PT:	Installation of Trimble TNL-2000 Approach Plus GPS for B-RNAV operation Owner: 99999 Scandinavian Avionics A/S
SA227-DC		



41-98	PT: OY-JRN	Installation of Trimble TNL-2000 Approach Plus GPS for B-RNAV operation
06.08.1998	BB-364	Owner: 99999 Scandinavian Avionics A/S
200	OY-JRN	
B200		
42-98	PT:	Installation of Single or Dual Trimble TNL-2101 I/O Approach Plus GPS for B-RNAV operation.
30.10.1998		Owner: 99999 Scandinavian Avionics A/S
550		
50-98	PT: OY-RAA	(Validation/extention of FAA STC No. ST 285CH to cover Model BAe 125 Series B as well
10.08.1998	258235	Owner: 99999 Scandinavian Avionics A/S
51-98	PT:	Installation of Garmin GPS 165 for B-RNAV operation
22.09.1998		Owner: 99999 Scandinavian Avionics A/S
SA226-AT		
SA226-T(B)		
SA227-AT		
SA227-TT		
52-2000	PT: OY-PHN	Installation of SKY 497, SKYWATCH with GNS 530 as Indicator
08.11.2001	209	Owner: 99999 Scandinavian Avionics A/S
Falcon10		
Falcon100		
52-98	PT:	Installation of Garmin GPS 165 for B-RNAV operation
22.09.1998		Owner: 99999 Scandinavian Avionics A/S
SA226-TC		
SA227-AC		
SA227-BC		
53-98	PT:	Installation of Garmin GPS 165 for B-RNAV operation
22.09.1998		Owner: 99999 Scandinavian Avionics A/S
SA227-DC		
54-2000	PT:	Installation of Allied Signal (Sundstrand) Ground Proximity Warning System (GPWS) inclusive CIC Barometric Altitude Rata Computer
21.09.2001		Owner: 99999 Scandinavian Avionics A/S
SA227-AC		
56-2000	PT: OY-OBC	Installation of BF Goodrich WX-500 Stormscope system including antenna
26.08.2003	421A0013	Owner: 99999 Scandinavian Avionics A/S
421A	OY-OBC	



57-2000 26.08.2003	PT: OY-OBC 421A0013	Installation of Garmin GNS 530 COM/NAV/GPS including antenna. BY installation of GNS as NAV 2, one CDI/OBS indicator is installed for NAV2. NAV1 connected for B-RNAV and continued IFR operation. Owner: 99999 Scandinavian Avionics A/S
421A	OY-OBC	
57-2001 16.03.2006	PT:	CAS 67A and dual MST 67A Owner: 99999 Scandinavian Avionics A/S
VFW-614		
58-2002 15.01.2003	PT:	Insallation of Artex C406-2 Emergency Locator Transmitter (ELT) and Antenna behind the aft pressure bulkhead. ELT control installed in the cockpit Owner: 99999 Scandinavian Avionics A/S
501		
59-2000 20.03.2000	PT:	Installation of GNS-430 System Owner: 99999 Scandinavian Avionics A/S
99		
6/92 07.05.1992	PT:	Installation of Fairchild type A100A CVR with ULD (p/n 93-A100-80) Owner: 99999 Scandinavian Avionics A/S
SC7 SKYVAN		
67-2001 03.12.2001	PT: OY-JPD 44-7995322	Installation of Garmin GPS 155XL with approval for Enroute - B-RNAV Owner: 99999 Scandinavian Avionics A/S
PA44-180		
68-2001 03.12.2001	PT: OY-PEL 28R8018024	Installation of Garmin GPS 155XL with approval for Enroute - B-RNAV Owner: 99999 Scandinavian Avionics A/S
PA28RT-201		
7/89 (Rev. 2) 10.01.1992	PT:	Installation of Cockpit Voice Recorder, Flight Data Recorder and Underwater Locater Device. Owner: 99999 Scandinavian Avionics A/S
550		
80-98 07.12.1998	PT:	Installation of Allied Signal KLN 90B GPS for B-RNAV operation. Owner: 99999 Scandinavian Avionics A/S
1900C		
9/98 (Rev. 1) 22.07.1998	PT:	Installation of Universal Solid-State Cockpit Voice Recorder (CVR) model CVR-30B Owner: 99999 Scandinavian Avionics A/S
222U		



DO-0150 FR172R	PT:	Installation of KX155 and HKI208/9 Owner: 01263 DANSK FLY ELEKTRONIK APS
DO-0411 19.04.2010 206	PT: D-EBIW	Installation of an Artex ME406 ELT w./ whip antenna on a Cessna 206 aircraft. U206-03896 Owner: 01263 DANSK FLY ELEKTRONIK APS
DO0041 206	PT:	Installation of an Artex ME406 ELT w./ whip antenna on a Cessna 206 aircraft. Owner: 01263 DANSK FLY ELEKTRONIK APS
EASA STC 01.01.2005 HS125-800B	PT:	Avionics Mobile Collins TCAS 4000 EASA STC Owner:
EASA STC 1 01.01.2005 HS125-800B	PT:	Avionics Mobile Honeywell TCAS (CAS67) EASA STC Owner:
EASA STC 2 01.01.2005 HS125-700B	PT:	Avionics Mobile MK VIII EGPWS EASA STC Owner:
EASA STC 3 01.01.2005 HS125-700B	PT:	Avionics Mobile Collins TCAS 4000 EASA STC Owner:
EASA.A.A.01025 13.10.2005 L410 UVP-E20	PT: OY-PBI 871936 OY-PBI OY-PBH	ELT 406 AFM for 2026473-EO-01 Owner: 63605 Scandinavian Avionics
EASA.A.A.01032 13.10.2005 320 340 340A 340B	PT: OY-BSO 340A-0666 OY-BSO	AFM supplements for 2027438-EO-03 and -05 Owner: 63605 Scandinavian Avionics
EASA.A.A.01034 14.10.2005 HS125-700 HS125-700A HS125-700B HS125-800 HS125-800A HS125-800B	PT: VP-CMP 257214 VP-CMP OY-MFL	ELT 406 AFM for 2025716-EO-02 Owner: 63605 Scandinavian Avionics



EASA.A.A.01035	PT: OO-SKV	Garmin GPS 400 Stand alone. AFM for
14.10.2005	0153	2026957-EO-01
		Owner: 63605 Scandinavian Avionics
500	OY-VIS	
550	OO-SKP	
560	OO-SKV	
S550		
EASA.A.A.01036	PT: LN-PBF	ELT 406 AFM for 2027785-EO-01
14.10.2005	208B0584	Owner: 63605 Scandinavian Avionics
208	LN-PBF	
208A		
208B		
EASA.A.A.01037	PT: OY-PBG	ELT 406 AEM for 2028154-EO-01
14.10.2005	0015	Owner: 63605 Scandinavian Avionics
404	OY-PBG	
406		
F406		
EASA.A.A.01068	PT: SX-BMG	TFM-138B VHF/FM installation AFM supplement for
04.01.2006	375	2023379-AM-01
		Owner: 63605 Scandinavian Avionics
DHC6-100	SX-BMG	
DHC6-200	SX-BVP	
DHC6-300		
EASA.A.A.01069	PT: I-PIAH	AFM supplement for 2026288-EO-03 ELT 406
18.11.2005	BB777	Owner: 63605 Scandinavian Avionics
200	I-PIAH	
B200	TF-FMS	
300	F-GICA	
300LW	ln-tw1	
B300	SE-KXM	
	OH-BSA	
	OH-BSB	
EASA.A.A.01070	PT: OY-BJP	ELT 406 AFM for minorchange 2027045-EO-01
18.11.2005	AC-499	Owner: 63605 Scandinavian Avionics
SA226-AT	oy-bjp	
SA227-AC		
SA227-AT		
SA227-BC		
SA227-DC		
SA226-TC		
SA226-T(B)		
SA26-AT		
EASA.A.A.01099	PT: YU-BSM	In-flight Entertainment System AFM supplement
13.01.2006	550-0808	Owner: 63605 Scandinavian Avionics
500	YU-BSM	
550	YU-BSG	
550BRAVO		
S550		



EASA.A.A.01099	PT: YU-BSM	In-flight Entertainment System AFM supplement
13.01.2006	550-0808	Owner: 63605 Scandinavian Avionics
560		
560ULTRA		
EASA.A.A.01108	PT: SE-IUC	AFM supplement for ELT minor change
25.06.2006	3447013	2029789-EO-03
		Owner: 63605 Scandinavian Avionics
PA34-200	SE-IUC	
PA34-200T		
PA34-220T		
EASA.A.A.01118	PT: LN-AWA	AFM ELT 406 for minor change 2030084-EO-01
30.01.2006	B-213	Owner: 63605 Scandinavian Avionics
100	LN-AWA	
99		
A100		
B100		
EASA.A.A.01132	PT: OY-ASY	ELT 406 AFM supplement for minor change
20.02.2006	110-308/19	Engineering Order 2025739-EO-01
		Owner: 63605 Scandinavian Avionics
EMB110P1	OY-ASY	
EMB110P2	OY-BHT	
EMP-110K1		
EASA.A.A.01159	PT: YU-BTT	ELT Kannad 406 AFM for 2030241-EO-01
02.03.2006	551-0038	Owner: 63605 Scandinavian Avionics
501	OY-PDN	
551	PH-DEZ	
	YU-BTT	
EASA.A.A.01215	PT: HA-YFE	Installation of ELT Kanad 406 AFM supplement
25.07.2006	A046SA	for minor change 2031558-EO
		Owner: 63605 Scandinavian Avionics
MU300	HA-YFE	
MU300-10	OH-KNE	
EASA.A.A.01226	PT: LN-AEY	Approval of AFM for minor change 2025849-EO-01
06.07.2006	31-457	Owner: 63605 Scandinavian Avionics
PA31-350	LN-AEY	
PA31	LN-LAS	
PA31-325	LN-NAB	
	LN-NPZ	
EASA.A.A.01230	PT: OY-PBW	Installation of Kanad ELT 406. AFM supplement
25.07.2006	SH3760	for 2026480
		Owner: 63605 Scandinavian Avionics
SD3-30	OY-MUG	
SD3-60	OY-PBW	
SD3-60SHERPA	G-BPFN	
SD3-SHERPA		

**EASA.A.A.01234****PT: DE-DYO**Replacement of Nicad Batt. with Concorde
Sealed Lead Acid Batt.

08.09.2006

Owner: 63605 Scandinavian Avionics

500	SE-DYO
550	
S550	
560	

EASA.A.A.01235**PT: SE-DYO**Installation of KLN 90B. AFM for minor change
S550-0134 2033991

31.07.2006

Owner: 63605 Scandinavian Avionics

500	SE-DYO
550	
S550	
560	

EASA.A.A.01236**PT: LN-BER**

AFM approval for minor change 2033451-EO

06.07.2006

8192

Owner: 63605 Scandinavian Avionics

DO228-100	LN-BER
DO228-101	LN-AAO
DO228-200	
DO228-201	
DO228-202	
DO228-212	

EASA.A.A.01335**PT: LN-TWL**Approved AFM supplement for AIM 1100 and
PS-835D installation on 2031449-EO

04.12.2006

BB-1144

Owner: 63605 Scandinavian Avionics

200	ln-tw1
B200	SE-LLU
B200C	SE-KOL
300	
B300	
300LW	
200C	
1900	
1900C	
1900D	

EASA.A.A.01346**PT: OY-RAA**AFM for minor change 2037403-EO. Upgrade of
UNS-1B+ to 602 software.

16.01.2007

258235

Owner: 63605 Scandinavian Avionics

HS125-700A
HS125-700B
BAe125-800A
BAe125-800B

EASA.A.A.01354**PT: D-CRAS**AFM approval for Minor change 2033234 MCH for
STC EASA.A.S.02654

24.01.2007

SH3744

Owner: 63605 Scandinavian Avionics

SD3-30	D-CRAS
SD3-60	D-CCAS
SD3-60SHERPA	
SD3-SHERPA	



EASA.A.A.01364	PT: SE-LNU	Approved AFM for EASA.A.S.02703
01.02.2007	949	Owner: 63605 Scandinavian Avionics
Jetstream3100	SP-KWF	
Jetstream3102		
Jetstream3103		
Jetstream3200		
Jetstream3201		

EASA.A.A.01438	PT: SE-BRK	AFM approval for minor change 2027746-EO for EASA STC EASA.A.S.01451
19.10.2007		Owner: 63605 Scandinavian Avionics
500	SE-RBK	
550		
S550		
550BRAVO		

EASA.A.A.01477	PT: OY-SVM	AFM for minor change 2038735-EO installation of GTX 330 with ELS
18.05.2007	17274818	Owner: 63605 Scandinavian Avionics
172	OY-SVM	
172A		
172C		
172D		
172E		
172G		
172I		
172K		
172L		
172N		
172M		
172P		
172Q		
172R		
172S		

EASA.A.A.01499	PT: SX-IFA	AFM supplement for minore Change 2039448
05.07.2007	49809	Owner: 63605 Scandinavian Avionics
717-200	SX-IFA	
DC9-30		
DC9-31		
DC9-21		
DC9-41		
DC9-50		
DC9-51		
DC9-81		
DC9-82		
DC9-83		
DC9-87		
MD90-30		
MD-88		
DC9-10		

EASA.A.A.01510	PT: D-IIVK	AFM supplement for minor change for GTX-330 do on 2039628-EO
23.08.2007	T303-0287	



Owner:63605 Scandinavian Avionics

T303 D-IIVK

EASA.A.A.01511 **PT:D-EHVM** AFM Supplement for minor Change 2039919-EO
23.08.2007 236 **Owner:63605** Scandinavian Avionics

35-33 D-EHVM
35-B33
35-C33
35-C33A
A36
A36TC
B36TC
E33
F33A
F33C
J35
N35
P35
V35
V35B
V35A

EASA.A.A.01536 **PT:OH-BAR** AFM supplement for GMA 340 Audio panel
06.07.2007 P-477 approved under minor change 2034279-EO
Owner:63605 Scandinavian Avionics

60 OH-BAR
A60
B60

EASA.A.A.01549 **PT: SX-DCI** AFM for minor change 2035111-EO MCH to
20.08.2007 0366 EASA.A.S.02791.
Owner:63605 Scandinavian Avionics

550BRAVO SX-DCI
560

EASA.A.A.01578 **PT:D-EGDT** AFM for minor change 2041403-EO installation
20.08.2007 of GTX 330
Owner:63605 Scandinavian Avionics

F182P D-EGDT
F182Q
FR182

EASA.A.A.01591 **PT:LN-FAO** AFM approval for minor change 2040892-EO
21.11.2007 148 installation of Kanad 406 ELT
Owner:63605 Scandinavian Avionics

ATR42-300 LN-FAO
ATR42-320 LN-FAR
ATR42-400 LN-FAP
ATR42-500
ATR42-200

EASA.A.A.01598 **PT:SE** AFM supplement for minor change 2019974-EO-06
18.09.2007 **Owner:63605** Scandinavian Avionics

525 G-EDCL
525A



EASA.A.A.01600 18.10.2007	PT: SE-DRS RK037	AFM supplement approval for minor change 2041473-EO Installation of Kannad 406 ELT Owner: 63605 Scandinavian Avionics
400 400A	SE-DRS	
EASA.A.A.01605 29.04.2008	PT: OY-EDP 650-014	AFM supplement approval for project 2040879-EO installation of CVR-30B Owner: 63605 Scandinavian Avionics
650	OY-EDP	
EASA.A.A.01645 13.11.2007	PT: D-ESLO	AFM supplement for Minor Change 2042205-EO. Installation of L3 Stormscope Owner: 63605 Scandinavian Avionics
SR20 SR22	D-ESLO	
EASA.A.A.01665 12.03.2008	PT: OY-JBJ 258358	AFM supplement for minor change 2043647-EO. Upgrade of CVR-30B to CVR-120 Owner: 63605 Scandinavian Avionics
Hawker 800XP	OY-JBJ	
EASA.A.A.01667 09.01.2008	PT: LN-FAQ 953	AFM for Minor change 2043249-EO Upgrade for TDR-94D's for ELS Owner: 63605 Scandinavian Avionics
Jetstream3102 Jetstream3201	LN-FAQ	
EASA.A.A.01668 15.05.2008	PT: OY-GFL R18200659	AFM approval for minor change 2041403-EO MCH Owner: 63605 Scandinavian Avionics
R182 182A 182 182B 182F 182H 182K 182M 182N 182N 182P 182Q 182R 182S 182T T182 TR182 T182T	D-EVMC	
EASA.A.A.01677 27.11.2007	PT: OE-GMS 341	AFM approval for minor change 2032349-EO Dual UNS-1E installation on EASA.A.S.02551 Owner: 63605 Scandinavian Avionics
Learjet35 Learjet35A	OE-GMS	



EASA.A.A.01705 19.12.2007	PT: G-BPFN SH-3747	Approval of AFM supplement for Minor change 2043204-EO. Installation of Dual Mode-S transponders Owner: 63605 Scandinavian Avionics
SD3-30 SD3-60 SD3-60SHERPA SD3-SHERPA	G-BPFN	
EASA.A.A.01724 25.02.2008	PT: HB-VOR 0473	AFM approval for EASA.A.S.01112R2 Owner: 63605 Scandinavian Avionics
525 525A	HB-VOR I-EDEM	
EASA.A.A.01756 28.05.2008	PT: SE-RCY 550-0302	AFM approval for minor change 2042607-EO for ELS (only) on dual MST 67A transponders Owner: 63605 Scandinavian Avionics
550		
EASA.A.A.01756R1 13.08.2008	PT: SE-RCY 550-0302	AFM approval for Minor change 2042607-EO. (Address was changed on R1) Owner: 63605 Scandinavian Avionics
550	SE-RCY	
EASA.A.A.01898 15.08.2008	PT: LY-RUS 340A-074	AFM supplement for Minor change 2047615-EO ELS for TDR-94 Owner: 63605 Scandinavian Avionics
SF340A SF340B	LY-RUS	
EASA.A.A.01942 14.10.2008	PT: SE-ISG 340B-162	AFM approval for minor change 2037470-EO. FMS UNS-1k+/1L Owner: 63605 Scandinavian Avionics
SF340A 340B SF340B	SE-ISG XA-TJI SE-KXJ	
EASA.A.A.02021 31.03.2009	PT: OY-JJO 267	AFM for ARTEX ELT on 2051086-EO Owner: 63605 Scandinavian Avionics
400A 400	OY-JJO	
EASA.A.S.00239 14.10.2004	PT:	EGPWS MK VIII Installation Owner: 63605 Scandinavian Avionics
400A	D-CEIS D-CLBA OE-GHM	
EASA.A.S.00239R1 15.02.2008	PT: D-CEIS RK010	STC for installation of Honeywell MK VIIIE. This STC is a EASA revision for correction of document references. Ammended with Minor Change 1 2017016-EO-02



Owner: 63605 Scandinavian Avionics

400A	OY-JJO		
EASA.A.S.00240	PT: D-CLBA	ELT installation	
14.10.2004	RK025		Owner: 63605 Scandinavian Avionics
400A	D-CEIS D-CLBA VP-CVP		
EASA.A.S.00241	PT: D-CLBA	ACAS installation	
14.10.2004	RK025		Owner: 63605 Scandinavian Avionics
400A	D-CLBA		
EASA.A.S.00294	PT: YR-TRG	ARTEX 406MHz ELT	
25.10.2004	835		Owner: 63605 Scandinavian Avionics
Jetstream3100	LN-FAC		
Jetstream3200	LN-FAN LN-FAZ LN-FAJ LN-FAM LN-FAV		
EASA.A.S.00294R1	PT: SX-BSR	ARTEX 406MHz ELT	
31.01.2006			Owner: 63605 Scandinavian Avionics
Jetstream3100	SX-IDI		
Jetstream3200			
Jetstream3201			
EASA.A.S.00295	PT:	EGPWS MK VI installation	
25.10.2004			Owner: 63605 Scandinavian Avionics
JETSTREAM3100	ES-PJG		
JETSTREAM3200	LN-FAJ LN-FAM LN-FAV		
EASA.A.S.00295R1	PT:	EGPWS MK VI installation	
31.01.2006			Owner: 63605 Scandinavian Avionics
Jetstream3100			
Jetstream3200			
EASA.A.S.00384	PT: D-CFAN	CVR-30B installation	
01.12.2004	258094		Owner: 63605 Scandinavian Avionics
HS125-800B	D-CFAN		
EASA.A.S.00438	PT: OY-HIF	406AF/AF-H Kannad ELT	
20.12.2004	47512		Owner: 63605 Scandinavian Avionics
222U	OY-HIF		
EASA.A.S.00438R1	PT:	406AF/AF-H Kannad ELT	
16.03.2006			Owner: 63605 Scandinavian Avionics
222	EI-DZN		
EASA.A.S.00456	PT:	VDL Mode 4 Transponder	
04.01.2005			Owner: 63605 Scandinavian Avionics
DHC7			



EASA.A.S.00456R1	PT:	VDL Mode 4 Transponder
16.03.2006		Owner: 63605 Scandinavian Avionics
DHC7		
EASA.A.S.00517	PT: YR-TRG	CAS 67A ACAS with dual MST 67A Mode-S Transponder
19.01.2005	835	Owner: 63605 Scandinavian Avionics
JETSTREAM3100	YR-TRG	
JETSTREAM3200	ES-PJG	
Jetstream3201	SX-BSR	
	SX-IDI	
	4X-CII	
EASA.A.S.00576	PT: SE-DDY	Honeywell CAS67A ACAS System including Dual MST 67A Mode-S Transponders
09.02.2005	550-0115	Owner: 63605 Scandinavian Avionics
500	EC-IMF	
550	OY-BZT	
560	I-JESO	
S550	SE-DDY	
560ULTRA	OO-SKP	
	SX-DCI	
EASA.A.S.00576R1	PT:	Honeywell CAS67A ACAS System including Dual MST 67A Mode-S Transponders
11.03.2005		Owner: 63605 Scandinavian Avionics
500	SE-RCI	
550	G-JETO	
560	I-ALKA	
S550	OY-CYV	
560ULTRA	SE-DYO	
	OY-ELY	
	OE-GCI	
	OY-VIS	
	G-RVHT	
	OO-SKV	
EASA.A.S.00576R2	PT: SE-DDY	Installation of Honeywell CAS 67A ACAS System including Dual MST 67A Mode-S Transponders
24.01.2006	550-0115	Owner: 63605 Scandinavian Avionics
500	YU-BSM	
550	F-HACA	
S550	OY-TMA	
550BRAVO	SE-DLZ	
560	F-HCRT	
560ULTRA		
EASA.A.S.00599	PT: LN-TFM	Stormscope WX-500 Installation
02.03.2005	P210-00026	Owner: 63605 Scandinavian Avionics
P210N	LN-TFM	
EASA.A.S.00609	PT: D-ILWB	EGPWS Mk VI, KMD 850 Multifunction Display and RDR2000 Weather Radar
01.03.2005		Owner: 63605 Scandinavian Avionics



EASA.A.S.00609	PT: D-ILWB	EGPWS Mk VI, KMD 850 Multifunction Display and RDR2000 Weather Radar
01.03.2005		Owner: 63605 Scandinavian Avionics
228-100	D-ILWB	
228-200		
228-201		
200-202		
228-202K		
228-213		
228-100		
EASA.A.S.0069	PT: YL-NST	F-1000 FDR
07.12.2004	258424	Owner: 63605 Scandinavian Avionics
HS125-800XP	YL-NST	
EASA.A.S.0069R1	PT: D-CFAN	F-1000 FDR
07.12.2004	258094	Owner: 63605 Scandinavian Avionics
HS125-800B	D-CFAN	
Hawker 800XP	OY-JBJ	
EASA.A.S.0074	PT: YL-NST	ELT 406
07.12.2004	258424	Owner: 63605 Scandinavian Avionics
HS125-800XP	YL-NST	
EASA.A.S.00747	PT: D-ISTC	Div installations
31.05.2005	MU-2B-40-4	Owner: 63605 Scandinavian Avionics
MU2B-40	D-ISTC	
EASA.A.S.0074R1	PT: D-CFAN	ELT 406
07.12.2005	258094	Owner: 63605 Scandinavian Avionics
HS125-800B	D-CFAN	
Hawker 800XP	OY-LKG	
EASA.A.S.00764	PT: D-IBBA	KMD 850 and SKY 899
13.06.2005	525-0025	Owner: 63605 Scandinavian Avionics
525	D-IBBA	
525A	D-IRON	
	D-IMPC	
	D-ICEY	
	D-IWIL	
EASA.A.S.00766	PT: SE-LSR	ADF 2
08.06.2005	0340A-078	Owner: 63605 Scandinavian Avionics
SF340A	SE-LSR	
EASA.A.S.00773	PT: I-PIAH	Instllation of GNS 430A/530A
29.06.2005	BB777	Owner: 63605 Scandinavian Avionics
B200	I-PIAH	
200	ln-twl	
	LN-NOA	
EASA.A.S.0097	PT: SX-DCI	DFDR Installation
06.08.2004	0366	Owner: 63605 Scandinavian Avionics



EASA.A.S.0097	PT: SX-DCI	DFDR Installation
06.08.2004	0366	Owner: 63605 Scandinavian Avionics
560ULTRA	SX-DCI	
EASA.A.S.0097R1	PT: SE-RCI	Installation of a L3 Digital Flight Data Recorder
03.01.2006	0678	Owner: 63605 Scandinavian Avionics
550	SE-RCI	
S550	SE-RGY	
560	D-CJJJ	
550BRAVO	VP-CJR	
560ULTRA	N404RK	
	G-OXJC	
	VP-CSN	
	YU-BZZ	
	OY-KLG	
	VH-WFE	
	F-HCRT	
EASA.A.S.01028	PT: SX-BTV	ACAS TCAS-4000
31.01.2005	124	Owner: 63605 Scandinavian Avionics
LEARJET55	SX-BTV	
EASA.A.S.01029	PT: SX-BTV	5 parameter F-1000 with pitot/static F-1000 FDR. Ammended with 2019630-EO-02 (location of recorder in the cabin and 15 parameters AFM approve by SA)
31.01.2005	124	Owner: 63605 Scandinavian Avionics
LEARJET55	SX-BTV	
LEARJET55C	OE-GCF	
	D-CWAY	
EASA.A.S.01032	PT: SX-BTV	EGPWS MK VIII
31.01.2005	124	Owner: 63605 Scandinavian Avionics
LEARJET55	SX-BTV	
LEARJET55C	OE-GCF	
	D-CWAY	
EASA.A.S.01058	PT: P4-AVN	TCAS-4000 with dual mode-S TDR-94D
30.05.2005	0128	Owner: 63605 Scandinavian Avionics
FALCON10	P4-AVN	
	OY-PHN	
EASA.A.S.01058R1	PT: P4-AVN	Installation of TCAS-400 incl. dual mode-S transponder TDR-94D
14.05.2007	0128	Owner: 63605 Scandinavian Avionics
Falcon10		
EASA.A.S.01059	PT: P4-AVN	ELT 406
30.05.2005	0128	Owner: 63605 Scandinavian Avionics
FALCON10	P4-AVN	
EASA.A.S.01059R1	PT: P4-AVN	Installation of Kannad 406 ELT
14.05.2007	0128	Owner: 63605 Scandinavian Avionics



EASA.A.S.01059R1	PT:P4-AVN	Installation of Kannad 406 ELT
14.05.2007	0128	Owner: 63605 Scandinavian Avionics
Falcon10	OY-PHN	
EASA.A.S.01060	PT:P4-AVN	MFRD and EGPWS MK VIII
30.05.2005	0128	Owner: 63605 Scandinavian Avionics
FALCON10	P4-AVN	
EASA.A.S.01060R1	PT:P4-AVN	Installation of MFRD and EGPWS MK VIII
14.05.2007	0128	Owner: 63605 Scandinavian Avionics
Falcon10		
EASA.A.S.01060R2	PT:	Installation of Honeywell MFRD and EGPWS MK VIII.
09.08.2007		Correction of typing error on issue 0 and 1
		Owner: 63605 Scandinavian Avionics
Falcon10	OY-PHN	
EASA.A.S.01091	PT:OY-PEB	Installation of Universal Taws system and related componets.
04.01.2007	BB-309	ADC 2000 and Altimeter
		Owner: 63605 Scandinavian Avionics
B200	OY-PEB	
200		
200C		
B200C		
EASA.A.S.01092	PT:OY-PEB	GPS TNL-2101 I/O APPR+
11.02.2005	BB-309	Owner: 63605 Scandinavian Avionics
200	OY-PEB	
B200		
EASA.A.S.01093	PT:OY-PEB	Dual mode-S transponder MST 67A
11.02.2005	BB-309	Owner: 63605 Scandinavian Avionics
200	OY-PEB	
B200	SE-KDK	
EASA.A.S.01093R1	PT:SE-KOL	Dual Mode-S transponder with ELS and EHS. MST 67A with PS578A or PS550
05.02.2007	FA-189	Owner: 63605 Scandinavian Avionics
200	SX-ECG	
B300	SE-LKY	
B200	SE-KOL	
200C	EC-JGB	
B200C		
300		
300LW		
B300C		
1900		
1900C		



EASA.A.S.01094	PT: OY-PEB	MFD-640 & RP-1008
11.02.2005	BB-309	Owner: 63605 Scandinavian Avionics
200	OY-PEB	
B200		
EASA.A.S.01109	PT: D-IDBW	Installation of KMH 980 (TCAS 1/EGPWS Class B) and KMD 850 (MFD)
11.04.2005	0044	Owner: 63605 Scandinavian Avionics
525	D-IDBW	
	F-HEQA	
EASA.A.S.01110	PT: D-IDBW	Stormscope WX-500
11.04.2005	0044	Owner: 63605 Scandinavian Avionics
525	D-IDBW	
	EC-KSB	
EASA.A.S.01111	PT: D-IDBW	KLN 94 GPS
11.04.2005	0044	Owner: 63605 Scandinavian Avionics
525	D-IDBW	
EASA.A.S.01112	PT: D-IDBW	GTX 330D Mode-S transponders
11.04.2005	0044	Owner: 63605 Scandinavian Avionics
525	D-IDBW	
	LX-LOV	
	F-HGOL	
EASA.A.S.01112R1	PT: OY-JMC	Installation of dual GTX 330D Mode S transponder systems with ELS and EHS.
31.05.2007	525-277	Owner: 63605 Scandinavian Avionics
525	OY-JMC	
525A	F-HALO	
	SE-RGX	
	F-GMDL	
EASA.A.S.01112R2	PT: HB-VOR	Dual GTX 330D with ELS and EHS. Additional AFM approved under EASA.A.A.01724
25.02.2008	0473	Owner: 63605 Scandinavian Avionics
525	HB-VOR	
525A	I-EDEM	
EASA.A.S.01132	PT: OY-CCJ	ACAS
31.05.2005	468	Owner: 63605 Scandinavian Avionics
LEARJET35A	OY-CCJ	
LEARJET35	D-CDSF	
	D-CONE	
EASA.A.S.01189	PT: OY-BZT	ELT 406 Kannad
07.04.2005	550-0259	Owner: 63605 Scandinavian Avionics
550	OY-GMK	
500	EC-IMF	
S550	SE-RCI	
560	G-JETO	
550BRAVO	OY-ELY	
560ULTRA	OY-BZT	

**EASA.A.S.01189****PT: OY-BZT**

ELT 406 Kannad

07.04.2005

550-0259

Owner:63605 Scandinavian Avionics

OO-SKP
CS-DDV
G-RVHT
SE-RGN
SE-DEG
OO-SKV

EASA.A.S.01189R1**PT: YU-BSM**

Installation of Kannad 406AF ELT

20.02.2006

550-0808

OBS modified with minor change 2022014-EO MCH

Owner:63605 Scandinavian Avionics

500 YU-BSM
550 SE-DYO
S550 SE-RGY
550BRAVO OE-GCI
560 SE-DDY
560ULTRA F-HACA
VP-CJR
SP-KBM
N66HD
SX-DCI
YU-BZZ
OY-TMA
N550BG
SE-DRZ
D-ICIA
F-HCRT

EASA.A.S.01190**PT: OY-JPJ**Installation of FreeFlight 2101 I/O Approach
Plus GPS Navigation System

25.08.2005

650-0060

Owner:63605 Scandinavian Avionics

650 OY-JPJ

EASA.A.S.01191**PT: OY-JPJ**Honeywell CAS 67A TCASII Sysstem, including
Dual MST 67A mode S Transponders

25.08.2005

650-0060

Owner:63605 Scandinavian Avionics

650 OY-JPJ
OY-NLA

EASA.A.S.01193**PT: OY-SVU**

Installation of Universal TAWS

26.07.0005

2063

Owner:63605 Scandinavian Avionics

ATP OY-SVU
OY-SVT
OY-SVI

EASA.A.S.01194**PT: OY-SVU**

Installation of UNS-1L (K+) FMS

26.07.2005

2063

Owner:63605 Scandinavian Avionics

ATP OY-SVU
OY-SVT
OY-SVI

**EASA.A.S.01216****PT: OH-BSB**

CAS67A ACAS & Mode-S.

30.05.2005

FA-206

Owner:63605 Scandinavian Avionics

300

S9-BAA

B300

OH-BSA

350

OH-BSB

300LW

SE-KOL

OY-CVB

EASA.A.S.01268**PT: OY-BJP**

Honeywell CAS 67A TCAS with dual MST 67A

17.07.2005

AC-499

Mode-S transponder.

(227-ST shall read SA227-AT see last page)

Owner:63605 Scandinavian Avionics

SA226-AT

G-BUKA

SA226-T(B)

SX-BNN

SA226-TC

oy-bjp

SA227-AC

SX-BBX

SA227-BC

SX-BMM

SA227-DC

VH-HAN

SA227-TT

SA227-AT

EASA.A.S.01271**PT: I-PIAH**

Installation of Dual mode-S transponder GTX

29.06.2005

BB777

330D

Owner:63605 Scandinavian Avionics

200

I-PIAH

B200

ln-twl

B300

OO-SAL

300

SE-KXM

B200C

OY-CKP

B300LW

EASA.A.S.01294**PT: VP-CMP**

Installation of a Rockwell Collins TCAS-4000

26.07.2005

257214

with dual TDR-94D Mode S Transponders

Owner:63605 Scandinavian Avionics

HS125-700A

VP-CMP

HS125-700

OY-MFL

HS125-700B

HS125-800

HS125-800A

HS125-800B

EASA.A.S.01349**PT: LN-TWL**

Installation of TAWS ST3400 system

20.02.2006

BB-1144

Owner:63605 Scandinavian Avionics

200

ln-twl

200C

B200

B200C

300

300LW

B300

EASA.A.S.01349R1**PT: SE-KOL**

Installation of ST3400

26.02.2007

FA-189

Owner:63605 Scandinavian Avionics

200

OH-BSA



EASA.A.S.01451 **PT: SE-DEG** Installation of GPS 400 in center panel with
24.01.2006 500-0276 GAD 42 adapter for roll steering
Owner: 63605 Scandinavian Avionics

550 SE-DEG
S550

EASA.A.S.01455 **PT: OY-BSO** Installation of GTX 330 Mode S Transponder
20.09.2005 340A-0666 **Owner: 63605** Scandinavian Avionics

310 D-IDOS
310K D-IFWA
310P SE-FZL
310Q OY-BSO
310R
T310P
T310Q
T310R
320
340
340A
335
401
401A
402
401B
402A
402B
402C
404
F406
411
411A
414
414A
421
421A
421B
421C
425
441

EASA.A.S.01472 **PT: D-IBCB** Installation of Cloud Research and Seeding
01.08.2005 BB 1729 System
Owner: 63605 Scandinavian Avionics

B200 D-IBCB

EASA.A.S.01472R1 **PT: D-IBCB** Installation of Cloud Research and Seeding
07.10.2005 BB 1729 System
Owner: 63605 Scandinavian Avionics

B200 D-IBCB

EASA.A.S.01537 **PT: I-AVEB** Installation of a Rockwell Collins TCAS-4000
15.11.2005 A0087SA with dual TDR-94D Transponders
Owner: 63605 Scandinavian Avionics

MU300 I-AVEB



EASA.A.S.01537 15.11.2005	PT: I-AVEB A0087SA	Installation of a Rockwell Collins TCAS-4000 with dual TDR-94D Transponders Owner: 63605 Scandinavian Avionics
	HA-YFE OH-KNE	
EASA.A.S.01561 22.11.2005	PT: OE-GTM RK343	Installation of L3 Digital FDR and Teledyne FDAU Owner: 63605 Scandinavian Avionics
400A	OE-GTM	
EASA.A.S.01587 22.02.2006	PT: OY-PBI 871936	Installation of Honeywell CCAS 67A TCAS II including dual MST 67A Mode S Transponder Owner: 63605 Scandinavian Avionics
L410 UVP-E20	OY-PBI OY-PBH	
EASA.A.S.01603 03.04.2006	PT: SE-IUC 3447013	Installation of KMD 850 Multi Function Display Owner: 63605 Scandinavian Avionics
PA34-200 PA34-200T PA34-220T	SE-IUC	
EASA.A.S.01625 20.02.2006	PT: OH-BBN E2497	Replacement of existing KI 525A HSI system with new KI 825 EHSI system Owner: 63605 Scandinavian Avionics
A36	OH-BBL OH-BBM OH-BBN OH-BBK	
EASA.A.S.01653 16.02.2006	PT:	Installation of dual GNS530 system Owner: 65096 Phoenix Aviation Design
Jetstream3202		
EASA.A.S.01701 13.02.2006	PT: OH-BBN E2497	GRAMIN GNS 430/530 upgrade for GPS approach Owner: 63605 Scandinavian Avionics
A36	OH-BBL OH-BBM OH-BBN OH-BBK	
EASA.A.S.02484 21.04.2006	PT: G-JETO 550-0441	Sandel ST3400 TAWS Installation Owner: 63605 Scandinavian Avionics
500 550 S550 560	G-JETO OE-GCI OY-BZT OK-SLS	
EASA.A.S.02484R1 02.04.2007	PT: SE-RBK 550-0315	Sandel ST3400 TAWS installation left or right hand installation Owner: 63605 Scandinavian Avionics
500 550	SE-RBK SE-DDY	



EASA.A.S.02484R1	PT: SE-RBK	Sandel ST3400 TAWS installation left or right hand installation
02.04.2007	550-0315	Owner: 63605 Scandinavian Avionics
S550	G-OXJC	
560	OO-SKV	
	SE-DLZ	
EASA.A.S.02499	PT:	Installation of AirCell ST3100
09.06.2006		Owner: 65639 STC Twenty One Ltd
550		
EASA.A.S.02509	PT: OY-PBW	Collins TCAS-94 with dual TDR-94D Transponder installation
07.06.2006	SH3760	Owner: 63605 Scandinavian Avionics
SD3-30	OY-MUG	
SD3-60	OY-PBW	
SD3-60SHERPA	S7-PAL	
SD3-SHERPA		
EASA.A.S.02530	PT: SE-DYO	Instalation of GNS 530A and KR 21
13.06.2006	S550-0134	Owner: 63605 Scandinavian Avionics
500	SE-DYO	
550		
S550		
560		
EASA.A.S.02551	PT: OE-GMJ	Installation of Dual Universal UNS-1E FMS
06.04.2006	504	Owner: 63605 Scandinavian Avionics
Learjet35	OE-GMJ	
Learjet35A	OE-GMS	
Learjet36		
Learjet36A		
EASA.A.S.02559	PT: LN-BER	Installation of ST-3400 TAWS
21.06.2006	8192	Owner: 63605 Scandinavian Avionics
DO228-100	LN-BER	
DO228-101	LN-AAO	
DO228-200	VT-EUM	
DO228-201		
DO228-202		
DO228-212		
EASA.A.S.02560	PT: LN-BER	Installation of Honeywell CAS 67A TCAS system with dual MST 67A Mode-S transponder
12.06.2006	8192	Owner: 63605 Scandinavian Avionics
DO228-100	LN-BER	
DO228-101	LN-AAO	
DO228-200		
DO228-201		
DO228-202		
DO228-212		
EASA.A.S.02626	PT: HA-YFE	Universal TAWS Installation incl. MFD-640
27.06.2006	A046SA	Owner: 63605 Scandinavian Avionics



EASA.A.S.02626	PT: HA-YFE	Universal TAWS Installation incl. MFD-640
27.06.2006	A046SA	Owner: 63605 Scandinavian Avionics
MU300	HA-YFE	
MU300-10	OH-KNE	
EASA.A.S.02627	PT: HA-YFE	Installation of Universal FMS UNS-1L (UNS-1K)
27.06.2006	A046SA	Owner: 63605 Scandinavian Avionics
MU300	HA-YFE	
MU300-10	OH-KNE	
EASA.A.S.02643	PT: SE-RGN	Installation of Dual GNS 430A/530A and 3rd
20.06.2007	500-0364	COMM Owner: 63605 Scandinavian Avionics
501		
551		
EASA.A.S.02644	PT: SE-RGN	Installation of Dual Garmin GNS 430A/530A and
20.06.2007	500-0364	3rd COMM Owner: 63605 Scandinavian Avionics
500	D-CIAO	
550	SE-RGN	
S550	F-HCRT	
EASA.A.S.02654	PT: OY-PBW	Honeywell EGPWS MK VI installation
06.07.2006	SH3760	Owner: 63605 Scandinavian Avionics
SD3-30	OY-MUG	
SD3-60	OY-PBW	
SD3-60SHERPA	D-CRAS	
SD3-SHERPA	D-CCAS	
	OY-PBV	
	G-BPFN	
	S7-PRI	
	S7-PAL	
EASA.A.S.02658	PT: OY-PBW	Trimble TNL-2101 I/O Approach+ GPS system
06.07.2006	SH3760	installation Owner: 63605 Scandinavian Avionics
SD3-30	OY-PBW	
SD3-SHERPA		
SD3-60SHERPA		
SD3-60		
EASA.A.S.02688	PT: OY-MFL	Installation of an Inflight Entertainment
22.03.2007	257103	system Owner: 63605 Scandinavian Avionics
HS125-600A	LN-ESA	
HS125-600B	OY-MFL	
HS125-700A		
HS125-700B		
BAe125-800A		
BAe125-800B		
Hawker 800		
Hawker 800XP		



EASA.A.S.02703	PT: OY-SVR	Sandel ST3400 TAWS Installation
21.07.2006	925	Owner: 63605 Scandinavian Avionics
Jetstream3100	OY-SVR	
Jetstream3102	OY-SVB	
Jetstream3103	SE-LNV	
Jetstream3200	OY-SVY	
Jetstream3201	OY-SVF	
	SE-LNU	
	LN-SVZ	
	SP-KWF	
	SP-KWE	
EASA.A.S.02728	PT: OY-NLA	Installation of Honeywell MFRD and as an option Honeywell Primus 400 Radar system.
11.09.2006	650-0070	OBS!! only applicabe for aircraft without EFIS and integrated MFD
		Owner: 63605 Scandinavian Avionics
650	OY-NLA	
EASA.A.S.02733	PT: OH-BAR	Installation of GNS 530 and GNS 430
.	P-477	Owner: 63605 Scandinavian Avionics
B60		
60		
A60		
EASA.A.S.02756	PT: OY-VIS	Installation of a "flight Display Systems" Entertainment System; DVD player, MAP computer and 2 LCD displays
31.08.2006	550-0672	Owner: 63605 Scandinavian Avionics
500	OY-VIS	
550		
560		
S550		
EASA.A.S.02774	PT: OH-BAR	Installation of GTX 330D with EHS
11.10.2007	P-477	Owner: 63605 Scandinavian Avionics
60		
A60		
B60		
EASA.A.S.02791	PT: SE-RGY	Installation of Honeywell MK VIII. Only for primus II and 1000. Ammeded with minor change 1 for new wiring and canged AFM. Including MCH 1 and 2 Including EOC-1 AFM approved under EASA.A.A.01549
03.11.2006	560-0414	Owner: 63605 Scandinavian Avionics
550BRAVO	SE-RGY	
560ULTRA	SX-DCI	
	CS-DTA	
EASA.A.S.02826	PT: OY-PBI	Honeywell EGPWS Mk VI installation
30.01.2007	871936	Owner: 63605 Scandinavian Avionics



EASA.A.S.02826	PT: OY-PBI	Honeywell EGPWS Mk VI installation
30.01.2007	871936	Owner: 63605 Scandinavian Avionics
L410 UVP-E20	OY-PBI	
	OY-PBH	
EASA.A.S.02832	PT: VP-CMP	Installation of a Universal Terrain Awareness Warning System (TAWS)
10.01.2007	257214	Owner: 63605 Scandinavian Avionics
HS125-700A	VP-CMP	
HS125-700B		
BAe125-800A		
BAe125-800B		
Hawker 800		
HS125-600A		
HS125-600B		
EASA.A.S.02833	PT: VP-CMP	Installation of Universal UNS-1F and / or UNS-1L FMS for B-RNAV, P-RNAV, Non-precision Approaches and Oceanic/ remote operations.
10.01.2007	257214	Owner: 63605 Scandinavian Avionics
HS125-600A	VP-CMP	
HS125-600B		
HS125-700A		
HS125-700B		
BAe125-800A		
BAe125-800B		
Hawker 800		
EASA.A.S.02852	PT: SX-BTN	Transponder Mode-S Elementary and EHS upgrade of existing dual diversity Mode-S installation Validated to FFA STC ST02686NY APR 01 2009.
03.01.2007	28494	Owner: 63605 Scandinavian Avionics
737-300	SX-BTN	
737-400	SX-BTO	
737-500	SX-BGH	
737-36E	SX-BGJ	
737-3M8	SX-BGK	
737-42C	SX-BBU	
737-430	SX-BGR	
737-46N	SX-BGS	
737-46Q	SX-BGV	
737-4Q8	EI-DGD	
737-4Y0	EI-CXL	
737-4S3	EI-CXI	
737-436	EI-CXJ	
737-4J6	EI-DGL	
	OY-JTD	
	OY-JTB	
	EI-CZG	
	EI-CXM	
	EI-DFE	
	EI-DFF	
	EI-DFD	
	EI-DMR	



EASA.A.S.02852 **PT: SX-BTN** Transponder Mode-S Elementary and EHS upgrade
03.01.2007 28494 of existing dual diversity Mode-S installation
Validated to FFA STC ST02686NY APR 01 2009.
Owner: 63605 Scandinavian Avionics

- EI-CWX
- EI-CWW
- EI-CWF
- EI-CWE
- D-AGMR
- EI-COK
- EI-COJ
- EI-COI
- EI-COH
- EI-CSU
- EI-CRZ
- F-GKTB
- F-GKTA
- OY-JTA

EASA.A.S.02853 **PT: OY-GGG** Installation of Honeywell Mk VIII EGPWS
13.02.2007 650-7039 **Owner:** 63605 Scandinavian Avionics

- 650
- OY-GGG
- OY-CLP

EASA.A.S.02861 **PT: OY-RAA** Installation of Honeywell Class A EGPWS .
03.01.2007 258235 Egpws for aircrafts equipped with a compatible
MFD or wather radar display
Owner: 63605 Scandinavian Avionics

- HS125-700A
- HS125-700B
- BAe125-800A
- BAe125-800B
- OY-RAA

EASA.A.S.02863 **PT: OY-BJP** Installation of Sandel ST 3400 TAWS.
18.12.2006 AC-499 Needs a GPS input with GPS ALT
Owner: 63605 Scandinavian Avionics

- SA226-TC
- SA227-AC
- SA227-BC
- oy-bjp
- EC-IRS
- EC-ITP
- EC-GPS
- SX-BBX
- SX-BMM
- EC-GEN

EASA.A.S.02872 **PT: VP-CMP** Mode S Transponder EHS upggrade for existing
09.01.2007 257214 Collins transponder system
Owner: 63605 Scandinavian Avionics

- Hawker 800
- Hawker 800XP
- HS125-700A
- HS125-700B
- BAe125-800A
- VP-CMP



EASA.A.S.02872 **PT: VP-CMP** Mode S Transponder EHS upggrade for existing
09.01.2007 257214 Collins transponder system
Owner:63605 Scandinavian Avionics

BAe125-800B

EASA.A.S.02872R1 **PT: OY-RAA** Mode S transponder upgrade for existinig
06.03.2007 258235 Collins transponder system
Owner:63605 Scandinavian Avionics

HS125-700A
HS125-700B
BAe125-800A
BAe125-800B
Hawker 800
Hawker 800XP

EASA.A.S.02872R2 **PT: OY-RAA** Mode S transponder upgrade for existing
06.03.2007 258235 Collins Transponder system including ELS and
EHS
Owner:63605 Scandinavian Avionics

HS125-700A OY-RAA
HS125-700B
BAe125-800A
BAe125-800B
Hawker 800
Hawker 800XP

EASA.A.S.02874 **PT: OY-BJP** Installation of a Garmin GPS 400 System for
14.12.2006 AC-499 B-RNAV and none presicion approach
Owner:63605 Scandinavian Avionics

SA226-TC oy-bjp
SA227-AC EC-GPS
SA227-BC SX-BBX
SX-BMM

EASA.A.S.02907 **PT: SX-DCI** EHS upgrade for existing Honeywell MST 67A
16.03.2007 0366 Transponder system.

See EASA.A.S.02907R1

Owner:63605 Scandinavian Avionics

500 SX-DCI
550 SE-DLZ
550BRAVO
S550
560
560ULTRA

EASA.A.S.02907R1 **PT: SX-BMK** EHS upgrade for existing Honeywell MST 67A
03.04.2007 907 transponder system. Requere PS 578A or PS 550
is installed and transponders is -2101

Owner:63605 Scandinavian Avionics

500 D-CIAO
550 EC-KBZ
550BRAVO SX-BMK
S550 F-HACA



EASA.A.S.02907R1	PT: SX-BMK	EHS upgrade for existing Honeywell MST 67A transponder system. Requere PS 578A or PS 550 is installed and transponders is -2101
03.04.2007	907	Owner: 63605 Scandinavian Avionics
560	SE-DLZ	
560ULTRA		
EASA.A.S.02948	PT: OY-GGG	Upgrade of existing MST-67A Transponder System for ELS and EHS
12.02.2007	650-7039	Owner: 63605 Scandinavian Avionics
650	OY-GGG	
	PH-MYX	
	D-CRRR	
	D-CCSD	
EASA.A.S.02953	PT: D-ICFM	Installation of GTX 330D with ELS and EHS
11.05.2007	425-0102	Owner: 63605 Scandinavian Avionics
425	D-ICFM	
EASA.A.S.02959	PT: F-HACA	Honeywell MFRD and optional Primus 300/400 Radar installation
16.02.2009	550-0182	Owner: 63605 Scandinavian Avionics
500		
550		
S550		
EASA.A.S.02975	PT: I-GASD	Installation of Honeywell TRA-45A Terrain Display/Radio Altimeter Indicator. OBS STC is only for S/N 650-0037
29.05.2007	650-0037	Owner: 63605 Scandinavian Avionics
650	I-GASD	
EASA.A.S.02976	PT: D-CRRR	Installation of ST3400 TAWS
04.04.2007	650-0187	Owner: 63605 Scandinavian Avionics
650	D-CRHR	
	D-CRRR	
EASA.A.S.03003	PT: OH-FAE	Installation of UNS-1L (K+)
13.04.2007	340A-139	Owner: 63605 Scandinavian Avionics
SF340A	OH-FAF	
340B	SE-ISG	
SF340B	XA-TJI	
	SE-KXJ	
EASA.A.S.03011	PT: SE-DYR	Installation of CAS 67A and dual Mode-S transponders with ELS and EHS
03.04.2007	551-0132	Owner: 63605 Scandinavian Avionics
501	SE-DYR	
551		
EASA.A.S.03013	PT: SE-KOL	Installation of Universal UNS-1L (-1K+) FMS
13.02.2007	FA-189	Owner: 63605 Scandinavian Avionics
200	SE-KOL	
200C		

**EASA.A.S.03013****PT: SE-KOL**

Installation of Universal UNS-1L (-1K+) FMS

13.02.2007

FA-189

Owner:63605 Scandinavian Avionics

B200
B200C
300
300LW
B300
B300C

EASA.A.S.03036**PT: SE-RGN**

Installation of a singel diversity Mode-S transponder with ELS and EHS

06.06.2007

500-0364

Owner:63605 Scandinavian Avionics

500

VP-BLV

SE-RGN

EASA.A.S.03107**PT: OY-CLP**

Mode S upgrade of existing Honeywell Transponders system RCZ-833 to comply with ELS and EHS

22.05.0007

650-7093

Owner:63605 Scandinavian Avionics

650

OY-CKE

OY-CLP

EASA.A.S.03107R1**PT: T7-VVI**

EHS on RCZ-833

20.07.2007

650-7090

Owner:63605 Scandinavian Avionics

650

T7-VVI

T7-VII

EASA.A.S.03154**PT: SE-DZZ**

STC for ST3400 TAWS (RH RMI)

22.02.2008

415

Owner:63605 Scandinavian Avionics

Learjet35
Learjet35A
Learjet31
LEARJET31A
Learjet36
Learjet36A

SE-DZZ

EASA.A.S.03227R1**PT: SX-IFA**

EHS upgrand for dual transponders installation. OBS aircraft must habe Minor change 2046341for ELS installed.

31.07.2008

49809

Owner:63605 Scandinavian Avionics

DC9-10
DC9-21
DC9-30
DC9-31
DC9-31
DC9-50
DC9-51
DC9-81
DC9-82
DC9-83
DC9-87
MD88
MD90-30
717-200

SX-IFA



EASA.A.S.03238	PT: OY-PDN	Installation of dual MST-67A with ELS and EHS
26.09.2007	551-0412	Owner: 63605 Scandinavian Avionics
501	OY-PDN	
551	SE-RCZ	
EASA.A.S.03308	PT: VP-CJR	Installation of Honeywell GNS-XLS FMS and Standby Gyro
28.11.2007	550-0354	Owner: 63605 Scandinavian Avionics
500	VP-CJR	
550	N550BG	
S550		
EASA.A.S.03373	PT: OH-KOG	STC for installation of dual Directional gyro's, EHSI KI-825 and Audio panels.
05.03.2008	642	Owner: 63605 Scandinavian Avionics
DHC6-200	OH-KOG	
DHC6-300		
DHC6-310		
EASA.A.S.03379	PT: SE-KXM	STC for Installation on Gramin GWX 68 and GMX 200 MFD for Radar and NAV display
30.01.2008	BB-459	Owner: 63605 Scandinavian Avionics
200	SE-KXM	
200C		
B200		
B200C		
300		
300LW		
B300		
B300C		
EASA.A.S.03384	PT: SE-KXM	STC for Installing GPS 500 with BRNAV
30.01.2008	BB-459	Owner: 63605 Scandinavian Avionics
200	SE-KXM	
200C		
B200		
B200C		
300		
300LW		
B300		
B300C		
EASA.A.S.03389	PT: G-CFBP	STC for installation of TAWS ST3400
30.05.2008		Owner: 63605 Scandinavian Avionics
HS125-700A	G-CFBP	
HS125-700B		
EASA.A.S.03424	PT: OY-PHN	STC for EHS upgrade of existing TDR-94D transponder system
22.02.2008	209	Owner: 63605 Scandinavian Avionics
Falcon10	OY-PHN	
Falcon100		



EASA.A.S.03460	PT:I-ULJA	STC for ELS/EHS for TDR-94 OBS only for PROLINE 4 equiped aircrafts
09.06.2008	380	Owner: 63605 Scandinavian Avionics
Falcon20-D	I-ULJA	
Falcon20-E5		
Falcon20-F5		
Falcon200		
Falcon20-C5		
Falcon20-D5		
Falcon20 GF		
Falcon20-E		
Falcon20-F		
Falcon20-G		
Falcon20-C		
EASA.A.S.03479	PT:OY-ATY	STC for installation of Honeywell MK VI EGPWS and TRA 45A Radio altitude instcator and Terrain display
28.03.2008	561	Owner: 63605 Scandinavian Avionics
DHC6-300	OY-ATY	
	OY-POF	
EASA.A.S.03482	PT:SE-KOL	STC for installation of 15 paremeter F1000 FDR. Alt/airspeed is interfaced electrical
05.05.2008	FA-189	Owner: 63605 Scandinavian Avionics
300	SE-KOL	
B300		
300LW		
B300C		
EASA.A.S.03483	PT:SE-KOL	STC for installation of CVR-30B
05.05.2008	FA-189	Owner: 63605 Scandinavian Avionics
300	SE-KOL	
B300		
300LW		
B300C		
200		
B200		
200C		
B200C		
EASA.A.S.03490	PT:OE-GLS	STC for P-RNAV upgrage of Universal UNS-1C sp to 1Csp+ FMS. OBS only valid for aircraft with Cessna approved B-RNAV UNS-1Csp system
25.08.2008	650-7110	Owner: 63605 Scandinavian Avionics
650	OE-GLS	
EASA.A.S.03544	PT:SE-RBO	STC for ELS and EHS upgrad of dual TDR-94 Mode-S transponder
11.06.2008	RK303	Owner: 63605 Scandinavian Avionics
400	SE-DRS	
400A	SE-RBO	



EASA.A.S.03563	PT: OY-FIN	Dual GNS530/430 with B-RNAV
17.06.2008	359	Owner: 63605 Scandinavian Avionics
114	OY-FIN	
114A		
114B		
112		
112B		
112TC		
112TCA		

EASA.A.S.03580	PT: VP-CMP	FDR-1000 5 parameter
15.06.2009	257214	Owner: 63605 Scandinavian Avionics
HS125-600A		
HS125-700		
HS125-700A		
HS125-700B		
HS125-800		
HS125-800A		
HS125-800B		
HS125-800XP		

EASA.A.S.03767	PT: F-GLPJ	EADI, EHSI, AHARS
29.06.2009	UC-40	Owner: 63605 Scandinavian Avionics
1900C	F-GLPJ	
200		
200C		
B200		
B200C		
300		
300LW		

EASA.A.S.03768	PT: F-GLPJ	Dual GNS 430AW/530AW only with SANDEL EHSI
29.06.2009	UC-40	Owner: 63605 Scandinavian Avionics
1900C	F-GLPJ	
200		
200C		
B200		
B200C		
300		
300LW		

EASA.A.S.03769	PT: D-CWAY	Dual UNS-1F Universal FMS
17.04.2009	0107	Owner: 63605 Scandinavian Avionics
LEARJET55A	D-CWAY	
LEARJET55B		
LEARJET55C		
Learjet55		

EASA.A.S.03790	PT: OY-PCD	KLN 90B B-RNAV
01.07.2009	213	Owner: 63605 Scandinavian Avionics
ATR42-200	OY-PCE	
ATR42-300	OY-PCD	
ATR42-320		



EASA.A.S.03849 **PT:D-ICIA** MST 67A ELS/EHS
29.06.2009 500-0086 **Owner:**63605 Scandinavian Avionics
500

EASA.A.S.03858 **PT:OY-JJO** Airshow 410 entertainment system
28.07.2009 RK267 **Owner:**63605 Scandinavian Avionics
400
400A

EASA.A.S.03894 **PT:F-GLPJ** Upgrade TDR-94D to ELS/EHS
16.06.2009 UC-40 **Owner:**63605 Scandinavian Avionics
1900C F-GLPJ
200
200C
B200
B200C
300
300LW
B300
B300C

EASA.A.S.0439 **PT:** Installation of two Collins TDR 94D
21.12.2004 **Owner:**66088 EISA
551

EASA.IM.A.S.0094R1 **PT:** Installation of RVSM
08.08.2004 Original Product Type Certification number:
FAA TC No. A22CE and A27CE owned by Star
Aviation, USA
Owner:
500 N18HJ
501 SE-RGN
550
551
S550
560

EASA.IM.A.S.01821 **PT:** ACSS T2CAS
28.11.2006 OBS EASA.IM.A.S.00762 must be done subsequent
Owner:64198 Raytheon Aircraft Services
1900C
1900D

EASA.IM.A.S.01950 **PT:** Replacement of Glareshield
12.05.2006 **Owner:**64062 Star Aviation
500 SE-RGN
501
550
551
S550
560



EASA.IM.A.S.02347 PT:- Auto pilot
2621 Owner:63060 Chelton Flight Systems
PA31-310

EASA.IM.A.S.02403 PT: Installation of S-TEC Manual electrical trim
15.06.2007 system, Model ST-619
Owner:01253 S-TEC CORPORATION
PA44-180

EASA.IM.A.S.02444 PT: STC for Proline 21
02.10.2008 Owner:01077 Rockwell Collins
300
B300
B300C

EASA.IM.A.S.02703 PT: DBU-5000 replacement of DBU-4000 or DBU-4100
15.10.2008 Owner:01077 Rockwell Collins
CL600-2A12
CL600-2B16
CL600-2B19
CL600-2C10
CL600-2D24
BD100-1A10
Falcon20-C5
Falcon20-D5
Falcon20-E5
Falcon20-F5
Falcon50
FALCON2000EX
G200
Learjet60
Hawker 800XP
Hawker 850XP
Hawker 900XP
400
400A
SAAB2000

EASA.R.A.01031 PT: **SX-HIN** AFM for ELT 406 in AS350/355 2023647-EO-01
13.10.2005 5406 Owner:63605 Scandinavian Avionics
AS350B SX-HIN
AS350B2 SX-HFA
AS350B3 SX-HFB
AS350BA SX-HEQ
AS355
AS355F1
AS355F2
AS355N
AS350B4
AS350B4
AS355E
AS355F

**EASA.R.A.01047****PT: OY-HAF**

VDL Mode 4. AFM for 2015555-EO-03

14.10.2005

61267

Owner:63605 Scandinavian Avionics

S61

OY-HAF

S61N

OY-HAG

EASA.R.A.01048**PT: OY-HIZ**

AFM for 2028478-EO-01 installation of TFM-138A

03.11.2005

3727

VHF FM Transceiver

Owner:63605 Scandinavian Avionics

AS350B

OY-HIZ

AS350B1

OY-HGN

AS350B2

OY-HGO

AS350B3

OY-HGP

AS350BA

OY-HGS

AS350BB

OY-HGR

EC130B4

OY-HGT

AS355E

LN-OMD

AS355F

LN-OEB

AS355F1

LN-OPA

AS355F2

LN-OAK

AS355N

LN-OGL

EASA.R.A.01057**PT: SX-HCK**

ELT Kannad 406 AFM for minor change

24.03.2006

593

2026780-EO-01

Owner:63605 Scandinavian Avionics

BO105

SX-HET

BO105 CBS-4

SX-HAY

BO105 LS A-1

SX-HMK

BO105 LS A-3

SX-HCK

BO105A

SX-HPA

BO105C

SX-HPC

BO105D

SX-HER

BO105S

BO105 CBS-5

EASA.R.A.01204**PT: LN-OBX**AFM approval for Observer Mk 111 System
installation on project number 2034623-EO

28.11.2006

2001

Owner:63605 Scandinavian Avionics

SA-330F

LN-OBX

SA-330G

SA-330J

AS332L

AS332L1

AS332C

EASA.R.A.01205**PT: LN-OBX**AFM approval for Installation of Honeywell KDM
150 GPS system on project number 2035176-EO

28.11.2006

2001

Owner:63605 Scandinavian Avionics

SA-330F

LN-OBX

SA-330G

SA-330J

AS332L

AS332C

AS332L1

**EASA.R.A.01206R1**

28.11.2006

PT:LN-OBX

2001

AFM approval for Installation of Homer, UHF
and Com audio switch system**Owner:**63605 Scandinavian Avionics

AS332C

LN-OBX

AS332L

AS332L1

SA-330F

SA-330G

SA-330F

SA-330J

EASA.R.A.01267

13.04.2007

PT: SX-HDA

7422

Approved AFM for 406 ELT on EO 2037656-EO

Owner:63605 Scandinavian Avionics

A109AII

A109C

A109E

A109

A109A

A109K2

A109LUH

A109S

A119

EASA.R.A.01353

05.12.2007

PT: SX-HDFInstallation of Artex 406 ELT. Approval of RFM
for Minor change 2037657**Owner:**63605 Scandinavian Avionics

BK117-C2

SX-HFE

BK117A-1

SX-HFD

BK117A-3

BK117A-4

BK117B-1

BK117B-2

BK117C-1

EASA.R.A.01354

14.11.2008

PT:LN-OCO

6420

RFM approval for Obsever installation on Minor
change 2017860-EO-02**Owner:**63605 Scandinavian Avionics

AS365N

AS365N2

AS365N3

AS365N1

EASA.R.A.01361

05.12.2007

PT:LN-OCO

6420

Approval for RFM for minor change 2017860-07
installation of Heel system**Owner:**63605 Scandinavian Avionics

SA365N

LN-OCO

SA365N1

AS365N2

AS365N3

EASA.R.A.01425

14.11.2008

PT:LN-OBX

2001

RFM for minor change 2035999 SATCOM system

Owner:63605 Scandinavian Avionics

AS332C

LN-OBX

AS332L



EASA.R.A.01425	PT:LN-OBX	RFM for minor change 2035999 SATCOM system
14.11.2008	2001	Owner: 63605 Scandinavian Avionics
AS332L1		
SA-330F		
SA-330G		
SA-330J		
EASA.R.A.01460	PT:F-HALB	Minor change for Audio panle PMA 7000 and Entertainment PXE 7300
04.04.2008	1394	Owner: 63605 Scandinavian Avionics
EC120B	F-HALB	
EASA.R.A.01461	PT:F-HALB	Minor change AFM approval for installation on TAS 600 and Movint terrain
04.04.2008	1394	Owner: 63605 Scandinavian Avionics
EC120B	F-HALB	
EASA.R.A.01502	PT:I-MAKO	AFM approval for Minor change 2022177-EO-01 to EASA.R.S.00684
21.08.2008	3693	Owner: 63605 Scandinavian Avionics
AS350B	I-MAKO	
AS350B1		
AS350B2		
AS350B3		
AS350BA		
AS350D		
AS355E		
AS355F		
AS355F1		
AS355F2		
AS355N		
AS355NP		
EASA.R.A.01536	PT:OY-HPI	AFM approval for ELT 406MHz Kannad on Minor change 2047800-EO
05.09.2008	45368	Owner: 63605 Scandinavian Avionics
206	OY-HPI	
206A	OY-HPJ	
206B	OY-HDC	
206L	SE-HOK	
206L-1		
206L4		
206L3		
EASA.R.A.01588	PT:F-HALB	RFM for 2042582-EO Radio Altimeter KRA 405B
05.03.2009	1394	Owner: 63605 Scandinavian Avionics
EC120B		
EASA.R.A.01590	PT:SE-HOJ	RFM for 2036829-EO
17.03.2009	760605	Owner: 63605 Scandinavian Avionics
S76A	SE-HOJ	
S76B	SE-JOB	
S76C	SE-JOJ	



M11/03 28.03.2003 200	PT: SE-LKY BL127 SE-LKY	Installation of Garmin GNS 430 Owner: 99999 Scandinavian Avionics A/S
M12/99 18.05.1999 EMB120ER	PT:	Installation of Universal UNS-1K for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
M16/00 06.07.2000 PA31	PT: SE-ITC 31-8012048 SE-ITC	Installation of two Garmin GNS 430 for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
M17/00 09.05.2000 690C	PT: SE-GSS 11613 SE-GSS	Installation of Garmin GNS 430 for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
M19/01 22.08.2001 550	PT: SE-RBM 0717 SE-RBM SE-RCI	Installation of Honeywell MK VIII Enhanced GPWS Owner: 99999 Scandinavian Avionics A/S
M22/01 18.09.2001 AS365N2	PT:	Installation of Cockpit Voice Recorder Universal CVR-30B Owner: 99999 Scandinavian Avionics A/S
M24/99 08.12.1999 JETSTREAM3100	PT: SE-FVP 719 SE-FVP	Installation of Sundstrand GPWS Mark II Owner: 99999 Scandinavian Avionics A/S
M25/99 15.12.1999 228-201	PT:	Installation of Sundstrand GPWS MK VI, Allied Signal KLN-90B as B-RNAV and Altitude Management System (AMS) Shadin AMS-2000 Owner: 99999 Scandinavian Avionics A/S
M27/98 17.02.1999 JETSTREAM3100	PT: SE-KHC 610 SE-KHC SE-LHP	Installation of Allied Signal GPWS Mark II Owner: 99999 Scandinavian Avionics A/S
M27/99 20.01.2000 PA28-181	PT:	Installation of Garmin GNS 430 as Basic-BRNAV equipment Owner: 01263 DANSK FLY ELEKTRONIK APS
M30/01 (Rev 1) 13.08.2002 SA227-AC	PT: SE-LEF AC-451B SE-LEF	Installation of Enhanced Ground Proximity Warning System (Without terrain display) Owner: 99999 Scandinavian Avionics A/S



M32/98 25.02.1999	PT:	Installation of Trimble TNL2000 Approach Plus for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
JETSTREAM3100	SE-LHP	
M36/01 11.02.2002	PT:	Installation of two GNS-430 as B-RNAV, one ART 2000 as Weather Radar and KMH-880/KTA-870 as Multi Hazard Awareness System/Traffic Advisory system Owner: 99999 Scandinavian Avionics A/S
MU2B-36		
M36/98 14.04.1999	PT:	Installation of Universal UNS-1Msp for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
FALCON10		
M38/01 19.12.2001	PT:SE-DLB 183	Installation of Altimeter, IS&S ADDU Owner: 99999 Scandinavian Avionics A/S
FALCON10 FALCON100	SE-DLB	
M5/99 12.04.1999	PT:	Installation of Trimble 2000 Approach Plus for European B-RNAV Owner: 99999 Scandinavian Avionics A/S
SD3-60		
RC1249 17.06.2004	PT:LN-OCO 6420	Collins HF-System Model HF-230 Easa STC 2004-6385 Owner: 63605 Scandinavian Avionics
AS365N2	LN-OCO	
RC1251 17.06.2004	PT:LN-OCO 6420	Homer System EASA STC 2004-6386 Owner: 63605 Scandinavian Avionics
AS365N2	LN-OCO	
RC1252 01.07.2004	PT:	Digital Kartensystem Owner: 63605 Scandinavian Avionics
EC135		
SA01267WI-D . . .	PT:	STC for Proline 21 Owner: 01077 Rockwell Collins
300 B300 B300C		
SA01420WI 06.04.2007	PT:N1252G 414-0809	FAA Validation and STC for EASA.A.S.01389 Owner: 63605 Scandinavian Avionics
402A 402B 402C F406 411		



SA01420WI	PT: N1252G	FAA Validation and STC for EASA.A.S.01389
06.04.2007	414-0809	Owner: 63605 Scandinavian Avionics
<hr/> 414 414A 421 421A 421B 421C 425 T310P T310Q T310R 310 310K 310Q 310P 310R 320 335 340 340A 340B 402 <hr/>		
SA01558CH-D	PT:	RVSM installation
03.05.2002		Owner:
<hr/> 501 SE-RBZ 551 HB-VJB OY-PDN SE-DYR <hr/>		
SA07-43	PT:	Canada Validation of EASA.A.S.01268 for TCAS CAS 67A and dual Transponder MST 67A
17.06.2008		Owner: 63605 Scandinavian Avionics
<hr/> SA226-AT SA226-TC SA226-T(B) SA227-AC SA227-AT SA227-DC SA227-TT <hr/>		
SA1026	PT:	Einbau eines Single-EFIS-Systems und eines Wetterradar systems
13.11.1997		Owner: 99999 Scandinavian Avionics A/S
<hr/> B60 <hr/>		
SA10810LA	PT:	T2CAS upgrade for aircraft that already have TCAS 2000 installed. (EASA Validated)
. . .		Owner: 64198 Raytheon Aircraft Services
<hr/> 1900D <hr/>		
SA1235	PT: D-IBFE	Einbau eines Collins TCAS-94 II, Universal
12.12.2001	1716	UNS-1K Flight



Owner:

200 D-IBFE

SA1282 **PT:** Einbau des Garmin Transponder GTX327,
11.09.2002 Audio/Marker GMA340 and Bendix/King DME KN-63

Owner:

B36TC

SA1292 **PT:** Einbau eines Airshow Entertainment Systems
07.10.2002 VIDAir-2000

Owner:99999 Scandinavian Avionics A/S

1900D

SA1312 **PT:** Einrüstung eines Universal Avionics UNS 1K
10.02.2003 Flight Management Systems

Owner:99999 Scandinavian Avionics A/S

B200
B300
300LW

SA1319 **PT: OE-BBB** Honeywell Integrated Hazard Aviodance Systems
10.04.2003 BB 526 (IHAS)

Owner:99999 Scandinavian Avionics A/S

B200 OE-BBB

SA2665CE **PT:** Collins TDR-94D and provision for installation
06.10.1999 of TCAS-94

Owner:

SD3-60

SA2669CE **PT:** TCAS II that requires installatioon in
06.10.1999 accordance with SA2665CE

Owner:

SD3-60

ST01392CH-D **PT:** RVSM installation

04.09.2002

Owner:

500 SE-RBM
550 OY-VIP
S550 N29EB
560 OY-JAI
OY-CYV
VP-BLV
OY-TMA
SE-DRZ

ST02437NY **PT:** FAA validation of EASA.A.S.01058R1

30.07.2007

Owner:63605 Scandinavian Avionics

Falcon10

ST02438NY **PT:** FAA validation of EASA.A.S.01060R2
09.08.2007 installation of Honeywell MFRD and EGPWS

Owner:63605 Scandinavian Avionics

Falcon10
Falcon10



ST02443NY. 06.08.2007	PT:	FAA validation of EASA.A.S.01059R1 Installation of 406 Kannard ELT Owner: 63605 Scandinavian Avionics
Falcon10		
ST02642AT 01.12.2004	PT:	RVSM installation Owner:
550	N18HJ	
ST02686NY 01.04.2009	PT: SX-BTN 28494	FAA validation of EASA.A.S.02852 ELS and EHS for MODE-S Transponders Owner: 63605 Scandinavian Avionics
737-300 737-400 737-500		
STC10026864R1 18.08.2009	PT: SE-DLZ 500-0411	GNS500 with P-RNAV installation Owner: 63605 Scandinavian Avionics
500 550	SE-DLZ	
STC10027014R0 31.08.2009	PT: D-ICIA 500-0086	Dual MST 67A Mode S transponders with ELS and EHS Owner: 63605 Scandinavian Avionics
500	D-ICIA	
STC10028068 30.11.2009	PT: OY-CLP 650-7093	Software upgrade, GNS-XL(S) to P-RNAV Limit to S/N 650-7001 thru 650-7119 Owner: 63605 Scandinavian Avionics
650	OY-CLP	
STC10028206 10.12.2009	PT: OY-HTV 4336	Digital Camera Installation incl. support. Owner: 63605 Scandinavian Avionics
R22BETA		
STC10028447R1 12.01.2010	PT: EI-DFP A319-112	Dual NAVAERO EFB Classe 2 Owner: 63605 Scandinavian Avionics
A318-100 A318-111 A318-112 A318-121 A318-122 A319 A320 A321 A320-214 A321-231 A320-232	TC-FBH TC-FBR	
STC10028591R0 27.01.2010	PT: LN-OOH 0399	AFM approval for GPS Data outlet, DME Antenna and DC-DC Converter, ref 2053562-EO Owner: 63605 Scandinavian Avionics
EC135-P1 EC135-P2	LN-OOE LN-OOH	

**STC10028591R0**

27.01.2010

PT:LN-OOH

0399

AFM approval for GPS Data outlet, DME Antenna
and DC-DC Converter, ref 2053562-EO**Owner:**63605 Scandinavian Avionics

EC135-P2+

EC135T1

EC135 T2

EC135-T2+

EC635 P2+

EC635 T1

EC635 T2+

TA0700

25.02.2003

PT:63605Installations eines Flight Management Systems
UNS 1B plus with GPS1000 Sensor**Owner:**99999 Scandinavian Avionics A/S

HS125-800B

TA0756

14.11.2003

PT:D-CEIS

RK010

Installation of Rockwell Collins TCAS-4000
incl. Dual Collins Mode-S Transponder TDR-94D
EASA STC 918**Owner:**63605 Scandinavian Avionics

400A

TA0757

22.10.2003

PT:D-CEIS

RK010

Installation of an Artex ELT 406
EASA STC 919**Owner:**63605 Scandinavian Avionics

400A

D-CEIS

TA0794

23.04.2004

PT:Installation of EGPWS MKVIII System
EASA STC 2004-4302**Owner:**

400A

TA0795

23.04.2004

PT:D-CHSW

RK084

Installation of EGPWS MKVIII System
EASA STC 2004-4303**Owner:**

400A

D-CHSW

TA0796

23.04.2004

PT:D-CHSW

RK084

Installation of a L3 Digital FDR STC EASA
2004-4304. Ammednde with minor change 1 on
2014341-EO-01**Owner:**63605 Scandinavian Avionics

400A

OY-JJO

TA0798

01.01.2004

PT:**Owner:**

500

TA0819

02.08.2004

PT: SX-DCI

0366

DFDR

Owner:63605 Scandinavian Avionics